





02-105-00750  
Location # 315406

REPORT OF UNDESIRABLE EVENT  
NTL-3A (EFFECTIVE MARCH 1, 1979)



To: District Manager, B.L.M., Fluid Minerals, P. O. Box 248, Craig, CO 81615  
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge \_\_\_\_\_ Blowout \_\_\_\_\_ Accident \_\_\_\_\_ Fire or Explosion \_\_\_\_\_
2. BBLS Discharged: 5 bbls Oil, 20 bbls Wtr. BBLS Lost: -0-
3. Contained on location: Yes X No \_\_\_\_\_
4. Date and time of event: 3/9/87 6:00 AM
5. Date and time reported to B.L.M.: Not Required
6. Location of event: U.P. 106X32 SWSW, Sec. 32, T2N, R102W, Rio Blanco County  
Rangely Weber Sand Unit, Rangely Field, Colorado
7. Specific nature and cause of event  
Leak in flowline
8. Describe resultant damage:  
N/A
9. Time required for control of event: ± 15 minutes
10. Action taken to control and contain:  
Shut off valve, sucked up fluid contained in catch basin, washed ditch with hot fresh water.
11. Action taken to prevent recurrence:  
Repaired flowline
12. Cause of death:  
N/A
- \*13. Other agencies notified:  
COLO. DEPT OF HEALTH, WTR QUALITY CONTROL, DENVER, CO - Written Report Only/ 3/9/87  
COLO. OIL & GAS CONSV. COMM, DENVER, CO - Written Report Only 3/9/87
14. Other pertinent information:  

  
Signature \_\_\_\_\_ Date 3/11/87  
T. L. Hurst  
Title Area Supervisor

\* A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.