



8-87-BCH 146
RECEIVED
SEP 10 1987
COLO. OIL & GAS CONS. COMM.
05-103-08766

Location # 315587

- Crack in flowline caused spill.

Title AREA SUPPLY

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.