




02469039



REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979)

COLO. OIL & GAS CONS. COMM.

05-163-07586

Location # 314938

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____

2. BBLS Discharged: 75 bbls injected water BBLS Lost: 60 bbls

3. Contained on location: Yes X No _____

4. Date and time of event: 8-8-87 12:30 P.M.

5. Date and time reported to BLM: N/A

6. Location of event: SWSW sec 26, T2N, R102W, Levison 34X
Rangely Weber Sand Unit, Rio Blanco County, Colorado

7. Specific nature and cause of event

Crack developed on flange weld.

8. Describe resultant damage:

9. Time required for control of event: _____

10. Action taken to control and contain:

High pressure DRA-E line shut in.

11. Action taken to prevent recurrence:-

Flange was re-welded.

12. Cause of death:

N/A

13. Other agencies notified:

[Redacted]
COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO - Written Report 8-10-87
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only 8-10-87

14. Other pertinent information:

Signature Wayne K Larsen Date 8-28-87
W.K. Larsen

Title Area Supervisor

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.