




REPORT OF UNDESIRABLE EVENT
NTL-3A (EFFECTIVE MARCH 1, 1979)



05-103-07718

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____

2. BBLS Discharged: 40 bbls wtr, 4 bbls oil BBLS Lost: 40 bbls wtr, -0- bbls oil

3. Contained on location: Yes X No _____

4. Date and time of event: 7/12/87 5:00 P.M.

5. Date and time reported to BLM: N/A

6. Location of event: A.C. McLaughlin 65X SWNW Sec 23, T2N, R103W
Rangely Weber Sand Unit, Rio Blanco County, Colorado

7. Specific nature and cause of event

Fiberglass line broke.

8. Describe resultant damage:

N/A

9. Time required for control of event: 15 minutes

10. Action taken to control and contain:

Shut line in, fluid ran down wash, recovered oil, water soaked into ground.

11. Action taken to prevent recurrence:

Repaired line.

12. Cause of death:

N/A

13. Other agencies notified:

COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO - Written Only 7/15/87
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only 7/15/87

14. Other pertinent information:

Signature T.L. Hurst Date 7/21/87
T.L. Hurst

Title Area Supervisor

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.