



REPORT OF UNDESIRABLE EVENT
NTL-3A (EFFECTIVE MARCH 1, 1979)

09-103-07402
LOCATION # 314847

To: District Engineer BLM, Bureau of Land Management, P. O. Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
2. BBLS Discharged: 200 Inj. Water _____ BBLS Lost: 200
3. Contained on location: Yes _____ No X
4. Date and time of event: 11/13/87 7:00 AM
5. Date and time reported to ^{BLM}~~USGS~~: 11/13/87 1:45 PM
6. Location of event: 50 yds. S. of UP 75X32, SE SE Sec 32, T2N, R102W
7. Specific nature and cause of event

Internal and external corrosion caused leak in line.

8. Describe resultant damage:

N/A

9. Time required for control of event: 20 min.
10. Action taken to control and contain:
Shut valve. Water went into Stinking Water Creek.
None recovered.
11. Action taken to prevent recurrence:
Replaced section of line.
12. Cause of death:
N/A

13. Other agencies notified:
Colorado Department of Health, Air Quality Control, Denver, Co.
Colorado Oil and Gas Conservation Commission, Denver, Co - Written Report Only

14. Other pertinent information:

Signature T. L. Hurst Date 11/18/87
T. L. Hurst

Title Unit Supervisor