

Document Number:  
400861747

Date Received:  
06/30/2015

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 96340 Contact Name: Linda Boone

Name of Operator: WIEPKING-FULLERTON ENERGY LLC Phone: (720) 941-0791

Address: 4600 S DOWNING ST Fax: \_\_\_\_\_

City: ENGLEWOOD State: CO Zip: 80113 Email: ldboonepar@aol.com

**For "Intent" 24 hour notice required,** Name: Sherman, Susan Tel: (719) 775-1111

**COGCC contact:** Email: susan.sherman@state.co.us

API Number 05-073-06156-00

Well Name: WITHERS Well Number: 10-12

Location: QtrQtr: SWNW Section: 10 Township: 12S Range: 54W Meridian: 6

County: LINCOLN Federal, Indian or State Lease Number: \_\_\_\_\_

Field Name: CROWS NEST Field Number: 13700

Notice of Intent to Abandon       Subsequent Report of Abandonment

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 39.019515 Longitude: -103.440036

GPS Data:  
Date of Measurement: 05/18/2009 PDOP Reading: 2.2 GPS Instrument Operator's Name: Joseph Dugan

Reason for Abandonment:  Dry     Production for Sub-economic     Mechanical Problems

Other \_\_\_\_\_

Casing to be pulled:  Yes     No      Estimated Depth: 6458

Fish in Hole:  Yes     No      If yes, explain details below

Wellbore has Uncemented Casing leaks:  Yes     No      If yes, explain details below

Details: \_\_\_\_\_

**Current and Previously Abandoned Zones**

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|-----------|-----------|-----------|----------------|---------------------|------------|
| CHEROKEE  | 6418      | 6424      |                | BRIDGE PLUG         | 6458       |

Total: 1 zone(s)

**Casing History**

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| SURF        | 12+1/4       | 8+5/8          | 24              | 383           | 200          | 383        |            | CALC   |
| 1ST         | 7+7/8        | 5+1/2          | 15.5            | 7,443         | 450          | 7,443      | 4,975      | CBL    |

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6390 with 2 sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:   
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged:

Perforate and squeeze at 460 ft. with 50 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged:   
 Set 15 sacks at surface  
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No  
 Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_  
 \*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_  
 Type of Cement and Additives Used: \_\_\_\_\_  
 Flowline/Pipeline has been abandoned per Rule 1103  Yes  No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Linda Boone  
 Title: Agent Date: 6/30/2015 Email: ldboonepar@aol.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Date: \_\_\_\_\_

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_ Expiration Date: \_\_\_\_\_

### Attachment Check List

| Att Doc Num | Name                    |
|-------------|-------------------------|
| 400861747   | FORM 6 INTENT SUBMITTED |
| 400861793   | WELLBORE DIAGRAM        |
| 400863118   | WELLBORE DIAGRAM        |

Total Attach: 3 Files

**General Comments**

| <b><u>User Group</u></b> | <b><u>Comment</u></b>  | <b><u>Comment Date</u></b> |
|--------------------------|--|----------------------------|
| Permit                   | Returned to draft for the following reason:<br>1) Proposed wellbore diagram showing plugging proposal is not attached. | 7/1/2015 8:07:22<br>AM     |

Total: 1 comment(s)