


US-103-05888
LOCH 3/4 5/5



TO: District Engineer, U.S. Geological Survey,
FROM: Texaco Inc., P.O. Box 2100, Denver, CO 80201
SUBJECT: Report of Undesirable Event

SPILL x DISCHARGE _____ BLOWOUT _____ ACCIDENT _____ FIRE OR EXPLOSION _____

1. Date and Time of Occurrence: 11:30 AM 6-4-87
2. Date and Time Reported to USGS: 4:15 PM 6-4-87
3. Location of Incident: 1000' SW of WCU #18
SE SE, Section 27, T3N-R94W
Rio Blanco County, Colorado
4. Surface Owner: Private - Helen Jensen
5. Lease Number: DEN-034110A
6. Specific Nature and Cause of Incident: External and internal corrosion
7. Description of Resultant Damage: Spill of approximately 5-10 bbls of crude oil.
8. Action Taken to Control Incident: Use of line was discontinued
9. Length of Time Required to Control Incident: Approximately 5 minutes.
10. Action Taken to Contain Discharged Fluids: Spilled fluids will be contained in containment pits.
11. Length of Time Required to Contain Discharged Fluids: Spilled fluids were contained at all times.
12. Action Taken to Cleanup: Vac trucks picked up spilled fluids from pit.
13. Length of Time Required for Cleanup: Clean up was completed 6-5-87.
14. Estimated Volume Discharged: Approximately 5-10 bbls oil
0 bbls water
15. Estimated Volume Lost: 0 bbls oil
0 bbls water
16. Action Taken to Prevent Recurrence: New line will be installed.
17. Other Federal or State Agencies Notified of Incident:
By Mail: BLM, OCCC, EPA, Colo. Dept. of Health
18. Comments:

SIGNATURE: *A.M. Medina*
TITLE: Area Superintendent

DATE: June 10, 1987