




02470159

Facility I.D.: 426403

REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979)



COLO. OIL & GAS CONS. COMM.

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill ☒ Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
2. BBLS Discharged: 75 BBLS Lost: 75
3. Contained on location: Yes ☒ No _____
4. Date and time of event: 6-21-87 1:00 A.M.
5. Date and time reported to BLM: Not required
6. Location of event: Main Water Injection Plant, SENE Sec 32, T2N, R102W
Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event

A 2" valve failed in a meter box.

8. Describe resultant damage:

9. Time required for control of event: 15 minutes

10. Action taken to control and contain:

A prepared dike started washing out, the dike was repaired with a backhoe. Vacuum trucks were called to drain the meter box until the

11. Action taken to prevent recurrence:-

repair was made.
The dike was built up sufficiently to prevent any reoccurrence.

12. Cause of death:

N/A

13. Other agencies notified:

6-22-87

COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO - Written report only
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only 6-22-87

14. Other pertinent information:

Signature

T.L. Hurst/gcn
T.L. Hurst

Date

6/24/87

Title Area Supervisor

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.