



July 13, 2015

Mr. Matt Lepore, Director
Colorado Oil & Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80203

**Re: Open Hole Logging Exception Request
Carlson A-15-16HN, API No. 05-123-41720**

This letter is a request for an exception to the Rule 317.p, of an Open Hole Logging requirement for the following well:

Operator:	Bayswater Exploration & Production, LLC
Well Name & Number:	Carlson A-15-16HN, API No. 05-123-41720
Surface Location:	NENE Sec 15-5N-65W
Form 2 Doc Number:	400830117

This request is based on adequate open hole well log control from the following two wells:

Caesar #1-14, API #123-12611, located ~943' NE of the subject well, and
Roth #14-5, API #123-20586, located ~1204' SE of the subject well

Both of these wells have open hole Dual Induction logs ran in them (COGCC Doc # 943036 and 1440628 respectively) that can be used to identify formation tops, bases and other stratigraphic markers by depth.

Operator will upon completion of the subject well and all other wells drilled from such pad report on the Form 5s for each well that no Open Hole logs were run per this exception request to Rule 317.p. Operator will obtain GR/Cement Bond logs from all new wells drilled from this pad that will be used to identify the setting depth of surface casing.

Thank you and please call the undersigned if you have any questions.

Mark E. Brown

Mark E. Brown
Operations Manager