

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Report Date <b>07/23/2015</b>
Document Number <b>400873242</b>

**OPERATOR'S MONTHLY REPORT OF OPERATIONS**  
**ERROR REPORT**

**OPERATOR INFO**

OGCC Operator Number: <u>100322</u>	Contact Name and Telephone:
Name of Operator: <u>NOBLE ENERGY INC</u>	Name: <u>REBECCA TRUJILLO</u>
Address: <u>1625 BROADWAY STE 2200</u>	Phone: <u>(303) 2284284</u> Fax: <u>( )</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>	Email: <u>Rebecca.Trujillo@nblenergy.com</u>

Summary Totals:

Total Error(s): 88 Total Modified(s): 0 Total Deleted(s): 0

Total 88 Error(s)

Report Month/Year: 05/2015

123-32573-00	NCLP PC AA 08-18 CN	NB-CD	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NB-CD; NEED 5A FOR NB-CD	
123-36684-00	KUMMER PC LE23-65-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: 5A WAS APPROVED FOR SIDETRACK 01	
123-36726-00	LONE PINE LB19-78HN NI	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE CURRENTLY ON HOLD	
123-37452-00	ROHN STATE LD03-62-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37453-00	ROHN STATE LD03-63HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37455-00	ROHN STATE LD03-65HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37457-00	ROHN STATE LD03-64HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37458-00	ROHN STATE LD03-66-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37462-00	ROHN STATE LD03-64-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	

123-37467-00	ROHN STATE LD03-65-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37471-00	ROHN STATE LD03-63-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37475-00	ROHN STATE LD03-62HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37476-00	ROHN STATE LD10-69HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37483-00	ROHN STATE LD03-66HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37617-00	ROHN STATE LD10-63HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37618-00	ROHN STATE LD10-67HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37619-00	ROHN STATE LD10-69-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37621-00	ROHN STATE LD10-65-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37622-00	ROHN STATE LD10-64-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37623-00	ROHN STATE LD10-63-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37624-00	ROHN STATE LD10-62HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment:	
123-37625-00	ROHN STATE LD10-64HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37626-00	ROHN STATE LD10-68-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	

123-37627-00	ROHN STATE LD10-68HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37628-00	ROHN STATE LD10-66-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37630-00	ROHN STATE LD10-67-1HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37631-00	ROHN STATE LD10-66HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-37637-00	ROHN STATE LD10-65HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38603-00	CUTTHROAT LC28-72HNB NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38604-00	CUTTHROAT LC28-73HNB NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38615-00	RAINBOW LC28-73-1HNA NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38618-00	TINA LC29-73-1HNA NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38619-00	RICO LC29-72-1HNA NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38620-00	TRISHA LC29-73HNB NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38621-00	RICO LC29-78-1HNC NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38622-00	TRISHA LC29-78HNB NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; NEED FORMS 5, 5A AND 10	
123-38623-00	TRISHA LC29-77HNB NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	

123-38776-00	RICO LC29-76-1HNA NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38777-00	RICO LC29-74-1HNA NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38778-00	TRISHA LC29-74HNB NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38779-00	TRISHA LC29-76HNB NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38780-00	TRISHA LC29-75HNB NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38781-00	TINA LC29-75-1HNA NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38782-00	TINA LC29-77-1HNA NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38851-00	CUTTHROAT LC28-77HNB NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-38856-00	BROOK LC28-77-1HNA NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39649-00	ELWAY ST LD01-74-1AHN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39652-00	ELWAY ST LD01-75-1BHN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39654-00	MCCAFFREY ST LD12-75-1BHN	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39663-00	MCCAFFREY ST LD12-75HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39672-00	MCCAFFREY ST LD12-74-1AHN	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	

123-39686-00	ELWAY STATE LD01-75HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39695-00	MECKLENBURG LD01-72-1AHN	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39698-00	SMITH ST LD12-72-1AHN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39699-00	MECKLENBURG LD01-73HN	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39700-00	MECKLENBURG LD01-73-1BHN	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39701-00	SMITH STATE LD12-73HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
[qtrqtr]	QQ/SEC/TWP/RANGE NOT FOUND OR IS NULL	Comment: SESE 1 9N 58W	
123-39703-00	SMITH ST LD12-73-1BHN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39758-00	NALEN ST LD12-76-1AHN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39760-00	NALEN STATE LD12-77HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39761-00	ATWATER ST LD01-76-1AHN	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39765-00	NALEN ST LD12-77-1BHN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5, 5A & 10 ARE IN PROCESS	
123-39766-00	ATWATER ST LD01-77HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39767-00	ATWATER ST LD01-77-1BHN	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	

123-39805-00	DAVIS ST LD02-72-1AHN NI	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39806-00	DAVIS STATE LD02-73HN NI	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39807-00	DAVIS ST LD02-73-1BHN NI	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39809-00	GRADISHAR ST LD11-73-1AHN	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39810-00	GRADISHAR ST LD11-72HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39812-00	GRADISHAR ST LD11-72-1BHN	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39814-00	UPCHURCH ST LD02-76-1AHN	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39817-00	UPCHURCH ST LD02-77-1BHN	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39819-00	SHARPE ST LD02-78-1AHN NI	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; NEED FORMS 5, 5A AND 10	
123-39820-00	SHARPE STATE LD02-77HN NI	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39828-00	MOSES STATE LD11-78HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39831-00	MOSES ST LD11-78-1BHN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39836-00	GONSOULIN ST LD11-76HN	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39844-00	MOSES ST LD11-77-1AHN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	

123-39852-00	SHARPE ST LD02-79-1BHN NI	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; NEED FORMS 5, 5A AND 10	
123-39872-00	LITTLE ST LD11-74-1BHN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39875-00	TRIPUCKA ST LD02-75-1BHN	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39877-00	LITTLE ST LD11-74HN NI	NBRR	PR
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39878-00	TRIPUCKA ST LD02-74-1AHN	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39879-00	TRIPUCKA ST LD02-75HN NI	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39896-00	MORTON STATE LD01-78-1AHN	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39898-00	MORTON STATE LD01-79HN NI	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	
123-39899-00	MORTON ST LD01-79-1BHN NI	NBRR	DG
[formation_code]	WELL DOES NOT MATCH OPERATOR	Comment: N-COM = NBRR; 5A IS CURRENTLY IN PROCESS	

Total 0 Modified(s)

Report Month/Year: /

	Comment:
--	----------

Total 0 Deleted(s)

Report Month/Year: /

	Comment:
--	----------