



STATE OF COLORADO
LAND AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
 SUITE 380 LOGAN TOWER BUILDING
 1580 LOGAN STREET

DENVER, COLORADO 80203

WILLIAM R. SMITH
 Director

(303) 866-3531

RICHARD D. LAMM
 Governor

FRANK J. PIRO
 Deputy Director

December 2, 1985

W. Jean Diendorf
 Pyramid Oil Co.
 10707 Norwalk Blvd.
 Santa Fe Springs, CA 90670

Dear Ms. Diendorf:

This is a follow-up letter to the one sent to Mr. Pat Parks of your office last May 15, 1985.

The following wells located in T33N-R12W have been found to have delinquent reports:

- Flynt #1 NESE 8-Completion Report(Form 5), past Sundry notice reports casing at different depths than Welex logs show. Need final plugging and cement verification report.
- Taylor #21-1 NESW 21-Geologic data required on back of Form 5.
- Herrera #5 SWSE 23-Form 5 and Notification of Clearance(Form 10)
- J.C.K. #4 SWSW23-Status:expired permit.
- Turner #3 NENW26-Submit a wellbore diagram of completion-including cemented zones.
- Ferguson2 #F-9 SESW26-Was casing perforated or mesh liner run?(diagram)
- Ferguson2 #F-10 SWSW 26- Surf. pipe set-Well drilled? Form 5 & status.
- Ferguson2 #F-11 SENE 33- Status, will rig remain here for the winter?
- Kroeger #K-8 SESW 33- Form 5 and Status report.
- Kroeger-Ferguson #3K-5- NESW 34- Form 5 and status.
- Kennedy #1 NWNE 17- Final plugging and cement verification report.
- Slade #1 SENE 18- Final plugging and cement verification report.
- Garris #1 NWNW 28-34N-13W- Form 5 (include Geo. tops)
- Taylor #LT30-1 SESW30-34N-13W- Final plugging and cement verification.
- Taylor #T3-4 NENE 3-33N-12W- Form 5, Form 10.
- Taylor #2 NESW 21-33N-12W- Form 5, status report.
- Ferguson2 #F-12:33N-12W- Form 5 and status report.(NENE 34)

The Commission is re-evaluating the use of pits in the State and we must have accurate records of your produced water. From my inspections this past summer it has become evident that water production is greater for several of your wells than indicated on our production reports.** The wells of concern are as follows:

- Taylor #1-A NESW 28-33N-12W
- Taylor #1 NESW 28
- Taylor #3 NESW 28
- Harris #1 and Harris #3 NESE28

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET

DENVER, COLORADO 80203

WILLIAM R. SMITH
Director

FRANK J. PIRO
Deputy Director

(303) 866-3531
December 2, 1985

RICHARD D. LAMM
Governor

Pits must be sized for the inflow amount of water and berms or ditch built to protect the pits from being filled by runoff water. This is particularly important for the Taylor wells. During my inspection of November 7, 1985 I observed the work done by the Harris lease. Please submit a sundry notice for this work for our record including plumbing diagram(New work). Send a Sundry notice when the pit work (enlargement, berm compaction) is completed for the Taylor wells.

Any questions concerning this matter should be directed to me at (303) 866-3531.

Yours Truly,

Stephan Pott
Petroleum Engineer

** Please send current water production for each well.

xc: Pat Parks