

Merrion Oil and Gas
LLOYD-FEDERAL #22-X-17

05-103-66126

08/03/2015

by Kyle P Granahan



Tank located at remote compressor location – tank missing required labels, battery sign has wrong operator name and information present, containment needs maintained.



Horizontal heated separator, gas meter, and compressor
on remote location



Well SI



DSCN1556



DSCN1557

Well head and plumbing layout SI, 2 gauges present both read 0 psi



DSCN1558



DSCN1559

Tanks on location have content and NFPA present but still missing required information.