

T2N, R66W

29

32

LAND 15C-32HZ
SURFACE LOCATION

SURFACE LOCATION: NAD 83
GROUND ELEVATION= 4909.4'
LATITUDE= 40.099275°
LONGITUDE= -104.797831°
LATITUDE= 40°05'57.392"
LONGITUDE= -104°47'52.191"
HEEL LOCATION: NAD 83
LATITUDE= 40.101284°
LONGITUDE= -104.799860°
LATITUDE= 40°06'04.622"
LONGITUDE= -104°47'59.494"
BOTTOM HOLE LOCATION: NAD 83
LATITUDE= 40.087492°
LONGITUDE= -104.799493°
LATITUDE= 40°05'14.971"
LONGITUDE= -104°47'58.175"

SURFACE LOCATION: NAD 27
LATITUDE= 40.099292°
LONGITUDE= -104.797304°
LATITUDE= 40°05'57.452"
LONGITUDE= -104°47'50.294"
HEEL LOCATION: NAD 27
LATITUDE= 40.101301°
LONGITUDE= -104.799333°
LATITUDE= 40°06'04.682"
LONGITUDE= -104°47'57.598"
BOTTOM HOLE LOCATION: NAD 27
LATITUDE= 40.087509°
LONGITUDE= -104.798966°
LATITUDE= 40°05'15.031"
LONGITUDE= -104°47'56.278"

S. 1/4 COR.
SEC. 32, T2N, R66W
FOUND 3 1/4" ALUM. CAP
L.S. NO. 14823

CENTER N. 1/16 COR.
SEC. 32, T2N, R66W
FOUND 2 1/2" ALUM. CAP
L.S. NO. 25937

CENTER COR.
SEC. 32, T2N, R66W
FOUND 2 1/2" ALUM. CAP
L.S. NO. 25937

NW. COR.
SEC. 32, T2N, R66W
FOUND 2 1/2" ALUM. CAP
WITNESS COR. 120' WEST
OF CORNER POSITION
L.S. NO. 13155

W. 1/4 COR.
SEC. 32, T2N, R66W
FOUND 2 1/2" ALUM. CAP
L.S. NO. 25937

SW. COR.
SEC. 32, T2N, R66W
FOUND 3 1/4" ALUM. CAP
L.S. NO. 17669

E. 1/4 COR.
SEC. 29, T2N, R66W
FOUND 2 1/2" ALUM. CAP
L.S. NO. 24670

NE. COR.
SEC. 32, T2N, R66W
FOUND 3 1/4" ALUM. CAP
L.S. NO. 25369

E 1/4 COR.
SEC. 32, T2N, R66W
FOUND 2 1/2" ALUM. CAP
ILLEGIBLE

SE. COR.
SEC. 32, T2N, R66W
FOUND 3 1/4" ALUM. CAP
L.S. NO. 13155


CERTIFICATE OF SURVEYOR:

THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM FIELD NOTES OF ACTUAL SURVEY MADE BY ME OR UNDER MY SUPERVISION AND THAT THE SAME ARE TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THIS CERTIFICATE DOES NOT REPRESENT A LAND SURVEY PLAT OR IMPROVEMENT SURVEY PLAT AS DEFINED BY C.S. 38-51-102 AND CANNOT BE RELIED UPON TO DETERMINE OWNERSHIP.

Benjamin J. Reenders
BENJAMIN J. REENDERS
PROFESSIONAL LAND SURVEYOR
COLORADO REGISTRATION NUMBER 4836
6/15/15

NOTICE:
ACCORDING TO COLORADO STATE LAW YOU MUST COMMENCE ANY LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THE DATE ON THE CERTIFICATION SHOWN HEREON.

NOTE:
MAGNETIC NORTH IS CURRENT AS OF 6/11/2015.
MAGNETIC NORTH CHANGES WEST 0°06' PER YEAR.



- ▲ INDICATES FOUND SECTION CORNER
- INDICATES CALCULATED CORNER
- ELEVATION BASED ON NAVD88 (GEOID09)
- BASIS OF BEARING DERIVED FROM COLORADO COORDINATE SYSTEM 1983 NORTH ZONE UNLESS OTHERWISE NOTED.
- ALL MEASURED DISTANCES ARE GRID.
COMBINED SCALE FACTOR: .99972835
- OPERATOR: ROB WILSON / PDOP = 1.3
- SEE ADDENDUM TO WELL LOCATION CERTIFICATE FOR EXISTING IMPROVEMENTS WITHIN 500' OF THE WELL PAD.
- WELL FOOTAGES ARE MEASURED AT RIGHT ANGLES TO THE SECTION LINES.
- THE BOTTOM OF HOLE BEARS S01°37'18"E 5025' FROM THE SURFACE LOCATION.



SCALE: 1" = 1000'

WELL PAD - LAND 15C-32HZ

LAND 15C-32HZ
WELL LOCATION CERTIFICATE
947' FNL & 1735' FEL NWNE (SURFACE)
217' FNL & 2301' FEL NWNE (HEEL)
50' FSL & 2212' FEL SWSE (BOTTOM)
LOCATED IN SECTION 32
T2N, R66W, 6TH P.M.
WELD COUNTY, COLORADO

Kerr-McGee Oil &
Gas Onshore L.P.
1099 18th Street
Denver, Colorado 80202



CONSULTING, LLC

SHERIDAN OFFICE
1095 Saberton Avenue
Sheridan, Wyoming 82801
Phone 307-674-0609

LOVELAND OFFICE
1635 Foxtrail Drive, Suite 204
Loveland, Colorado 80538
Phone 970-776-4331

DRAFTED BY:	MDZ	CHECKED BY:	BJR
DATE DRAFTED:	6/15/15	DATE SURVEYED:	3/24/15
REVISED:		FILE NAME:	13-113