

Michael L. Brown

From: "Scott Webb" <ScottW@whiting.com>
To: <ld_brown@bresnan.net>; <ml_brown@bresnan.net>
Sent: Monday, October 19, 2015 7:06 AM
Subject: FW: Razor 12F-0101A - API # 05-123-38713-00 - Sidetrack Request
From: Diana Burn - DNR [mailto:diana.burn@state.co.us]
Sent: Sunday, October 18, 2015 7:05 PM
To: Cole Orley
Cc: Scott Webb; Unit 409; Dirk Sutphin - DNR; Holly Taylor - DNR; Barbara Westerdale - DNR
Subject: RE: Razor 12F-0101A - API # 05-123-38713-00 - Sidetrack Request

Please proceed as proposed – what is the intended formation?

Thanks,
Diana

From: Cole Orley [mailto:Cole.Orley@whiting.com]
Sent: Sunday, October 18, 2015 6:31 PM
To: Diana Burn - COGCC (diana.burn@state.co.us)
Cc: Scott Webb; Unit 409
Subject: Razor 12F-0101A - API # 05-123-38713-00 - Sidetrack Request

SIDETRACK REQUEST**RAZOR 12F-0101A – API 05-123-38713-00****PROPOSED OR COMPLETED OPERATIONS:**

Diana,

We have drilled most of the lateral out of our desired target formation. We would like to open hole sidetrack the lateral to re-drill the lateral in our target formation.

TOTAL DEPTH REACHED:

13,830' (MD) 5,781' (TVD)

CASING:

SURFACE CASING:

SIZE 9-5/8" 36PPF J-55 LTC

DEPTH 1,899.9'

INTERMEDIATE CASING:

SIZE: 7" 32PPF HCL-80 LTC

DEPTH: 6,696.8'

DESCRIPTION OF FISH IN THE HOLE:

NO FISH TO REPORT

PLUG BACK DEPTH:

NO PLUG FOR OPENHOLE SIDETRACK

SIDETRACK KICK OFF POINT:

7,722' (MD), 6,101' (TVD)

BHL TARGET FOR SIDETRACK HOLE:

(SAME TARGET) 6,080'(TVD), 600' FNL AND 165'FWL S01-T10N-R58W

VERBAL APPROVAL TO SIDETRACK:

PENDING

Cole Orley

Regional Drilling Manager

Whiting Petroleum Corporation

and its wholly owned subsidiary

Whiting Oil and Gas Corporation

1700 Broadway, Suite 2300

Denver, CO 80290

Direct (303) 390-4259

Fax (303) 390-4972

cole.orley@whiting.com

www.whiting.com

The information contained in this message may be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please notify us immediately by replying to this message and deleting it from your computer.