



October 2, 2015

SYNERGY RESOURCES CORPORATION - #10311
20203 HIGHWAY 60
PLATTEVILLE, CO 80651

RE: Rule 317.s. Statewide Fracture Stimulation Setback

TC Country Club West 1-9-11

SHL: 2454'FNL, 1195'FEL, SENE Sec. 8-T5N-R66W,

Top of Producing Zone Location: 680'FNL, 460'FWL, Sec. 9-T5N-R66W

BHL: 931'FNL, 2481'FWL, Sec. 11-T5N-R66W

Dear Operator,

Extraction Oil & Gas, LLC (Extraction) is applying to the Colorado Oil and Gas Conversation Commission (COGCC) to drill the above referenced well at the described surface and bottom hole locations. Per COGCC Rule 317.s., no horizontal wellbore lateral shall be located less than one hundred fifty (150) feet from any existing or permitted oil or gas wellbore unless waived in writing by the operator of the encroached upon well. As currently planned, the horizontal wellbore lateral of the above well will lie within 150 feet of the wellbore of the captioned well:

SRC GCC #11-11D, API # 05-123-34539, Operated by Synergy, Closest distance: 1 foot

Per COGCC Rules, Extraction is required to get the offset well operator's approval in writing and a waiver of said Rule 317.s. The well is planned as above to maximize mineral recovery. Also enclosed is a Well Location Plat that shows the planned wellbore.

Should you find this acceptable please indicate so by signing the below section and returning the signed letter either via email to alyssa.andrews@iptenergyservices.com or by fax. Please contact the undersigned at 720-420-5700 with any questions.

Sincerely,

Alyssa Andrews
Operations Engineer
Integrated Petroleum Technologies
Consultant for Extraction Oil & Gas, LLC

I, Dan Bumbach, officer, agent, or employee of Synergy Resources Corp
operator of the affected well, with full power to execute the following, do hereby approve of the **Extraction TC**
Country Club West 1-9-11 well as listed above in **Sec. 8-T5N-R66W** and grant a waiver COGCC Rule 317.s. granting
that this well may drilled as planned.

Signed Dan Bumbach this ¹²13 day of October, 2015