

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

## BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found.  
Step 2. Sample now, if intermediate or surface casing pressure >25 psi. In sensitive areas, 1 psi.  
Step 3. Conduct Bradenhead test.  
Step 4. Conduct intermediate casing test.  
Step 5. Send report to BLM within 30 days and to OGCC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. OGCC Operator Number: 10084						11. Date of Test: 10-14-15	
2. Name of Operator: Pioneer Natural Resources						12. Well Status: <input checked="" type="checkbox"/> Flowing <input type="checkbox"/> Shut In	
3. BLM Lease No:						<input type="checkbox"/> Gas Lift <input type="checkbox"/> Pumping <input type="checkbox"/> Injection	
4. API Number: 25-071-07870-0000						<input type="checkbox"/> Clock/Intermittent	
5. Multiple completion? <input type="checkbox"/> Yes <input type="checkbox"/> No						<input type="checkbox"/> Plunger Lift	
6. Well Name: Loretto						13. Number of Casing Strings: <input checked="" type="checkbox"/> Two <input type="checkbox"/> Three <input type="checkbox"/> Liner?	
7. Location (QtrQtr, Sec, Twp, Rng, Meridian): S4SE 9 34S 66W							
8. County: Las Animas							
9. Field Name: Purgatoire River							
10. Minerals: <input checked="" type="checkbox"/> Fee <input type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/> Indian							
14. STEP 1: EXISTING PRESSURES							
Record all pressures as found	Tubing: Fm: <u>0</u>	Tubing: Fm:	Prod. Casing: Fm: <u>1</u>	Intermediate Csg: Fm:	Surface Casing: Fm: <u>0</u>	15. STEP 2: See instructions above.	

16. STEP 3: BRADENHEAD TEST									
Buried valve? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Confirmed open? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Elapsed Time (Min:Sec)	Fm: Tubing:	Fm: Tubing:	Production Casing PSIG	Intermediate Casing PSIG	Bradenhead Flow:
With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals. Define characteristics of flow in "Bradenhead Flow" column using letter designations below: O = No Flow; C = Continuous; D = Down to 0; V = Vapor H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas				00:	<u>0</u>		<u>1</u>		<u>0</u>
				05:					
				10:					
				15:					
				20:					
				25:					
BRADENHEAD SAMPLE TAKEN? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid				30:					
Character of Bradenhead fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black <input type="checkbox"/> Other: (describe)				Note instantaneous Bradenhead PSIG at end of test: >					
Sample cylinder number:									

17. STEP 4: INTERMEDIATE CASING TEST									
Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No		Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No		Elapsed Time (Min:Sec)	Fm: Tubing:	Fm: Tubing:	Production Casing PSIG	Intermediate Casing PSIG	Intermediate Flow:
With gauges monitoring production casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals. Characterize flow in "Intermediate Flow" column using letter designations below: O = No Flow; C = Continuous; D = Down to 0; V = Vapor H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas				00:					
				05:					
				10:					
				15:					
				20:					
				25:					
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid				30:					
Character of intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black <input type="checkbox"/> Other: (describe)				Note instantaneous Intermediate Casing PSIG at end of test: >					
Sample cylinder number:									

18. Comments: No flow on Bradenhead	

## 19. STEP 5: See instructions above.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed by: Bryan Magrino Title: \_\_\_\_\_ Phone: 719-859-0514Signed: Bryan Magrino Title: \_\_\_\_\_ Date: 10-14-15

WITNESSED BY: \_\_\_\_\_ Title: \_\_\_\_\_ Agency: \_\_\_\_\_