

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



**Report Date**  
**11/30/2015**

**Document Number**  
**400917953**

**OPERATOR'S MONTHLY REPORT OF OPERATIONS**  
**ERROR REPORT**

**OPERATOR INFORMATION**

|   |  |
|---|--|
| OGCC Operator Number: <u>16700</u>                        | Contact Name and Telephone:                  |
| Name of Operator: <u>CHEVRON USA INC</u>                  | Name: <u>Rose Washington</u>                 |
| Address: <u>6001 BOLLINGER CANYON RD</u>                  | Phone: <u>(713) 432-6248</u> Fax: <u>( )</u> |
| City: <u>SAN RAMON</u> State: <u>CA</u> Zip: <u>94583</u> | Email: <u>mwas@chevron.com</u>               |

Summary Totals:

Total Error(s): 0 Total Modified(s): 25 Total Deleted(s): 0

Total 0 Error(s)

Report Month/Year: /

Comment:

Total 25 Modified (s)

Report Month/Year: 08/2015

| OGCC Operator Number | Well Name                 | Operator | Classification                                | Category |
|----------------------|---------------------------|----------|---|----------|
| 045-14406-00         | 608108/1 SKR-598-35-AV-10 |          | WMFK  | TA       |
| [MODIFIED] MODIFIED  |                           |          | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |          |
| 045-15897-00         | 610836/1 SKR-598-36-BV-01 |          | WMFK  | TA       |
| [MODIFIED] MODIFIED  |                           |          | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |          |
| 045-16393-00         | 610838/1 SKR-598-36-BV-05 |          | WMFK  | TA       |
| [MODIFIED] MODIFIED  |                           |          | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |          |
| 045-16929-00         | 611056/1 SKR-598-36-BV-22 |          | WMFK  | TA       |
| [MODIFIED] MODIFIED  |                           |          | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |          |
| 045-16930-00         | 610842/1 SKR-598-36-BV-13 |          | WMFK  | TA       |
| [MODIFIED] MODIFIED  |                           |          | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |          |
| 045-16931-00         | 610843/1 SKR-598-36-BV-15 |          | WMFK  | TA       |
| [MODIFIED] MODIFIED  |                           |          | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |          |
| 045-16932-00         | 610844/1 SKR-598-36-BV-17 |          | WMFK  | TA       |
| [MODIFIED] MODIFIED  |                           |          | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |          |

|                     |                           |   |    |
|---------------------|---------------------------|---|----|
| 045-16933-00        | 610845/1 SKR-598-36-BV-19 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16934-00        | 610846/1 SKR-598-36-BV-21 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16935-00        | 610840/1 SKR-598-36-BV-09 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16936-00        | 610841/1 SKR-598-36-BV-11 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16937-00        | 610839/1 SKR-598-36-BV-07 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16938-00        | 610837/1 SKR-598-36-BV-03 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16939-00        | 611055/1 SKR-598-36-BV-20 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16940-00        | 611054/1 SKR-598-36-BV-18 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16941-00        | 611045/1 SKR-598-36-BV-02 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16942-00        | 611053/1 SKR-598-36-BV-16 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16943-00        | 611060/1 SKR-598-36-BV-12 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16944-00        | 611046/1 SKR-598-36-BV-04 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16945-00        | 611047/1 SKR-598-36-BV-06 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16966-00        | 611049/1 SKR-598-36-BV-10 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |

|                     |                           |   |    |
|---------------------|---------------------------|---|----|
| 045-16967-00        | 611048/1 SKR-598-36-BV-08 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-16968-00        | 611061/1 SKR-598-36-BV-14 | WMFK  | TA |
| [MODIFIED] MODIFIED |                           | Comment: N-COM=WMFK; NEED FORM 5A FOR 00 WMFK |    |
| 045-22131-00        | 618785/1 SKR-598-08-BV-04 | WMFK  | IJ |
| [MODIFIED] MODIFIED |                           | Comment: LOT 8 8 5S-98W                       |    |
| 045-22132-00        | 618783/1 SKR-598-08-BV-02 | WMFK  | IJ |
| [MODIFIED] MODIFIED |                           | Comment: LOT 8 8-5S-98W                       |    |

Total 0 Deleted(s)

Report Month/Year: /

---

|  |          |
|--|----------|
|  | Comment: |
|--|----------|