

Tammie:

Here's what we found on the UP 34-31 return to service:

UP 34-31 was returned to service on 11/21/2015, following a line replacement and wagskid installation.

James Francis performed the static test; 1783# for 15 minutes. No leaks.

Sorry for the delay on the info.

Rick M. LaNoue

Rangely Maintenance Planner

970-675-3723, Fax 675-3800, Cell 970-629-2992