

Inspector Name: Binschus, Chris

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/21/2015

Document Number:

682400167

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	440974	440974	Binschus, Chris	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED
☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	ALL INSPECTIONS
Andrews, Doug		doug.andrews@state.co.us	

Compliance Summary:

QtrQtr: SENE Sec: 1 Twp: 5N Range: 65W

Inspector Comment:

This is a construction inspection.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
440971	WELL	XX	02/27/2015		123-41205	LDS 1W-414	CI	<input checked="" type="checkbox"/>
440972	WELL	XX	02/27/2015		123-41206	LDS 1V-234	CI	<input checked="" type="checkbox"/>
440973	WELL	XX	02/27/2015		123-41207	LDS 1V-334	CI	<input checked="" type="checkbox"/>
440975	WELL	XX	02/27/2015		123-41208	LDS 1W-314	CI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>4</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>7</u>	Separators: <u>4</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>3</u>	Oil Tanks: <u>12</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Inspector Name: Binschus, Chris

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 440974

Site Preparation:

Lease Road Adeq.: SATISFACTORY

Pads: _____

Soil Stockpile: SATISFACTORY

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Data retrieval failed for the subreport 'Subreport1' located at: \\10.12.100.15\FarmReports\Insp\InspCOA.rdlc. Please check t

S/AR: _____ Comment: Operator did not give COGCC 48 hours notice prior to construction. See COGCC comments.

CA: _____ Date: _____

Wildlife BMPs:

Data retrieval failed for the subreport 'Subreport2' located at: \\10.12.100.15\FarmReports\Insp\InspBMP.rdlc. Please check t

S/AR: _____ Comment: Construction BMP-Fencing Requirements: No fence or gate constructed at location. See COGCC comments.

CA: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
DITCHES	Yes		

S/A/V: ACTION
REQUIRED

Corrective Action: Stormwater ditches need to be cleared. See COGCC comments. Date: 12/30/2015

Comments: Erosion BMPs: Ditches have been installed around perimeter of location; however, ditches need to be maintained. See COGCC comments.

Other BMPs: _____

Comment: _____

Staking:**On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 440971 Type: WELL API Number: 123-41205 Status: XX Insp. Status: CI

Inspector Name: Binschus, Chris

Facility ID: 440972	Type: WELL	API Number: 123-41206	Status: XX	Insp. Status: CI
Facility ID: 440973	Type: WELL	API Number: 123-41207	Status: XX	Insp. Status: CI
Facility ID: 440975	Type: WELL	API Number: 123-41208	Status: XX	Insp. Status: CI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

The subreport 'rptInsp13' could not be found at the

COGCC Comments

Comment	User	Date
The below BMP has not been performed. Operator may need to contact COGCC staff to address issue.	binschusc	12/23/2015
604c.(2).M. Fencing Requirements: The completed wellsites will be surrounded with a fence and gate. PDC personnel will monitor the wellsites regularly upon completion of the wells. Authorized representatives and/or PDC personnel shall be on-site during drilling and completion operations.		
Operator did not provide notice to COGCC 48 hours prior to commencing construction of this Oil and Gas Location. This will be forwarded onto OGLA for further review.	binschusc	12/23/2015
Remove soil material from topsoil stockpile by Corrective Action date of December 30, 2015. Refer to attached photo 5 in Doc.#682400170.	binschusc	12/23/2015
Stormwater BMPs installed around perimeter of location; however, ditches need to be maintained. The northern and western ditch have been filled with sediment from scraping during muddy conditions. Stormwater ditches need to be cleared of sediment from scraping operations by Corrective Action date of December 30, 2015. Refer to attached photos 4 and 7 in Doc.#682400170.	binschusc	12/22/2015

Attached Documents

You can go to COGCC Images ([https://cogcc.state.co.us/weblink/](https://cogcc.state.co.us/webblink/)) and search by document number:

Inspector Name: Binschus, Chris

Document Num	Description	URL
682400170	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3747817