

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400910896

Date Received:

12/28/2015

Spill report taken by:

YOUNG, ROB

Spill/Release Point ID:

441818

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>FOUNDATION ENERGY MANAGEMENT LLC</u>	Operator No: <u>10112</u>	Phone Numbers
Address: <u>16000 DALLAS PARKWAY #875</u>		Phone: <u>(918) 526-5591</u>
City: <u>DALLAS</u>	State: <u>TX</u>	Mobile: <u>(918) 636-7239</u>
Zip: <u>75248-6607</u>		Email: <u>regulatory@foundationenergy.com</u>
Contact Person: <u>Caitlin O'Hair</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400839515

Initial Report Date: 05/14/2015 Date of Discovery: 05/13/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWSW SEC 36 TWP 2N RNG 47W MERIDIAN 6Latitude: 40.091364 Longitude: -102.583658Municipality (if within municipal boundaries): _____ County: YUMA

Reference Location:

Facility Type: PIPELINE☐ Facility/Location ID No _____☐ No Existing Facility or Location ID No.☒ Well API No. (Only if the reference facility is well) 05-125-11946

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): UnknownEstimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0Specify: Unable to fully determine amount of water leak due to rain and rain puddles.

Land Use:

Current Land Use: CROP LAND Other(Specify): _____Weather Condition: Continuous rainfall throughout weekSurface Owner: FEE Other(Specify): RMR Ranch Inc., - Donald Ruteledge

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A water line leaked yesterday evening 200 yards East of RMR Ranch #14-36 (API#05-125-11946). Foundation Energy Management, LLC. called the COGCC and spoke to Rob Young (COGCC Inspector) on going forward with getting the line cleaned up. As per the spill requirements, Foundation contacted the landowner and Yuma LEPC of the spill. The determination of how much was spilled is unknown because of the present of rainwater on the location's surface. The well has been shut in and the line isolated. A backhoe is scheduled to get on site to repair the line today (if it can make it down from Sterling) and we are getting a vac truck to suck up the standing water/rainwater.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
5/14/2015	COGCC	Rob Young	303-252-0126	Called by phone and discussed moving forward on drying out the site and sampling.
5/14/2015	Yuma LEPC	yumaoem@wycomm.org	928-317-4680	Notified of spill via email.
5/14/2015	Landowner	Donald Ruteledge	303-570-1836	Talked to crew onsite.

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Caitlin O'Hair

Title: HSE/Regulatory Tech Date: 12/28/2015 Email: regulatory@foundationenergy.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

400910896	FORM 19 SUBMITTED
400910899	ANALYTICAL RESULTS
400960220	ANALYTICAL RESULTS

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

Environmental	Unchecked "corrective actions completed" per Operator.	12/31/2015 2:23:13 PM
---------------	--	--------------------------

Total: 1 comment(s)