

STATE OF
COLORADO

Young - DNR, Rob <rob.young@state.co.us>

Wright Landfarm project update and request for closure

2 messages

Carter Peace <cpeace@tasman-geo.com>

Wed, Dec 30, 2015 at 6:57 AM

To: "Young - DNR, Rob" <rob.young@state.co.us>

Cc: Rodney Reynolds <Reynoldsr@berexco.com>, mlindstrom@tasman-geo.com

Operator: Beren Corporation (#7800)**Facility Name: Wright Landfarm (Facility ID# 107607)****Site Legals: SWSW S31 T3S R53W 6PM****API # 05-121-05259****Wright Landfarm (REM# 7368)**

Hello Rob,

On behalf of Beren Corporation (Beren), Tasman Geosciences, Inc.(Tasman) is submitting this project update and request for closure of the Wright Landfarm location (Figure 1).

The removal and hauling for disposal of impacted soils began at the Wright landfarm 10/8/2015 and was completed 10/9/2015. Nine loads totaling approximately 186 Cubic Yards (cy) were hauled to the Waste Management Conservation Services Inc. (CSI) disposal facility in Bennett, Colorado under Beren waste manifests. Please see attached scanned copies of manifests for review.

Landfarm confirmation samples were collected Monday 12/28/15 to confirm that impacted soils had been completely removed from the landfarm area. CON01 and CON02 (Confirmation 01 and 02) were collected on the north and south end of the landfarm area respectively. The two confirmation samples exhibited concentrations below COGCC Table 910-1 standards for Total petroleum hydrocarbons – Diesel range organics, Sodium adsorption ratio, Electrical conductivity, and pH. Please see attached Wright Landfarm Confirmation Analytical Summary-Table 1 and the corresponding laboratory analytical report.

The landfarm area within the active tank battery will be in use as an access road. During plugging and abandonment activities the area will be contoured to match pre-existing conditions, seeded, and reclaimed in accordance with the COGCC 1000 Series Reclamation Regulation.

Based on the analytical data and waste manifest documentation included Beren is requesting a no further action (NFA) determination for this site.

Please contact me with any questions about this project,

Thank you,

Carter Peace

Operations Manager

Tasman Geosciences

6899 Pecos Street - Unit C

Denver, CO 80221

Cell 303 854 7337

Office 303 487 1228



5 attachments



Wright Landfarm.jpg
68K



Wright Landfarm Site Location-Figure 1.pdf
74K



Wright Landfarm Waste Disposal Manifests.pdf
1416K



Wright Landfarm Confirmation Analytical Summary-Table 1.pdf
94K



1512216 - Wright.pdf
289K

Young - DNR, Rob <rob.young@state.co.us>
To: Carter Peace <cpeace@tasman-geo.com>

Wed, Jan 13, 2016 at 9:48 AM

Carter,

The COGCC has reviewed the project update and request for closure for the Wright Landfarm (Rem #7368). Based on the information presented, it appears that no further action is necessary at this time and the COGCC approves the request for closure. However, should future conditions at the site indicate contaminant concentrations in soils exceeding the COGCC Table 910-1 Concentration Levels, further investigation and/or remediation may be required.

Remediation project #7368 has been changed to closed status.

Thank you,

Robert J. Young
Environmental Protection Specialist



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

P 303.252.0126 | C 720.471.1304 | F 303.252.0472

1120 Lincoln Street, Suite 801, Denver, CO 80203 rob.young@state.co.us | www.colorado.gov/cogcc

[Quoted text hidden]