

BONANZA CREEK ENERGY OPERATING CO
PO BOX 21974
BAKERSFIELD, California

State Seventy Holes 34-31-6 HNB

Ensign 136

Post Job Summary

Cement Intermediate Casing

Date Prepared: 9/27/13
Version: 1

Service Supervisor: PICKELL, CHRISTOPHER

Submitted by: LANSDALE, JUSTIN

HALLIBURTON

HALLIBURTON

Wellbore Geometry

Job Tubulars					MD		TVD		Shoe Joint Length ft
Type	Description	Size in	ID in	Wt lbm/ft	Top ft	Bottom ft	Top ft	Bottom ft	
Open Hole Section	8 3/4" Open Hole Section		8.750		475.00	6,797.00	475.00	6,266.00	
Casing	7" Intermediate Casing	7.00	6.276	26.00	0.00	6,797.00	0.00	6,266.00	41.86
Casing	Surface Casing	9.63	8.921	36.00	0.00	475.00			

HALLIBURTON


Pumping Schedule

Stage /Plug #	Fluid #	Fluid Type	Fluid Name	Surface Density lbm/gal	Avg Rate bbl/min	Surface Volume	Downhole Volume
1	1	Spacer	MUD FLUSH III	2.5	0.00	24.0 bbl	24.0 bbl
1	2	Cement Slurry	EconoCem B3	6.0		558.0 sacks	558.0 sacks
1	3	Cement Slurry	ExpandaCem B1	6.0		252.0 sacks	252.0 sacks
1	4	Spacer	Mud Displacement	6.0			258.0 bbls

HALLIBURTON

Data Acquisition

STATE SEVENTY HOLES 34-31-6 HNB 7" INT



DH Density (ppg) PS Pump Press (psi) Comb Pump Rate (bbl/min)

① Start Job 8.19;28,0 ④ Pump Mudflush 8.3;190;2.3 ⑦ Pump Expandacem 14.6# 13.26;53;3.9 ⑩ Pump Displacement 13.67;-9;0 ⑬ Check Floats 8.35;2987;0
 ② Test Lines 8.15;84;0 ⑤ Pump Water 8.32;370;5 ⑧ Shutdown 14.87;70;2.7 ⑪ Displ Reached Cmmt 8.35;424;8.5 ⑭ End Job 8.35;-1;0
 ③ Pump Water 8.18;-4;0 ⑥ Pump Econocem 12.5# 8.34;404;5 ⑨ Drop Top Plug 13.53;-9;0 ⑫ Bump Plug 8.38;2171;3

▼ HALLIBURTON | iCem® Service

Created: 2013-09-20 18:59:46, Version: 2.0.606

Edit

Customer: BONANZA CREEK ENERGY
 Representative: CHRISTOPHER PICKELL

Job Date: 9/20/2013 7:05:42 PM
 Sales Order #: 900758649

Well: STATE SEVENTY HOLES 34-31-6 HNB

HALLIBURTON

Service Supervisor Reports

Job Log

Date/Time	Chart #	Activity Code	Pump Rate	Cum Vol	Pump		Pressure (psig)	Comments
09/20/2013 12:45		Depart Yard Safety Meeting						SAFETY MEETING TO DISCUSS ROUTE TO LOCATION. INCLUDING TRAFFIC HAZARDS AND DETOURS DUE TO FLOODS
09/20/2013 13:00		Depart from Service Center or Other Site						LEAVE THE YARD FOR LOCATION
09/20/2013 15:30		Arrive At Loc						ARRIVE AT LOCATION. RIG HAD 35 JOINTS OF CASING LEFT TO RUN
09/20/2013 18:45		Pre-Rig Up Safety Meeting						SAFETY MEETING TO DISCUSS SPOTTING IN EQUIPMENT AND RIGGING UP. RIG DONE RUNNING CASING AT 1900
09/20/2013 19:00		Rig-Up Equipment						SPOT IN ON DOG HOUSE SIDE OF RIG AND RIG UP BULK TRUCKS, WATER LINE, AND IRON TO THE WELL
09/20/2013 19:50		Pre-Job Safety Meeting						SAFETY MEETING TO WITH ALL ON LOCATION TO DISCUSS JOB SAFETY AND PROCEDURE
09/20/2013 20:10		Start Job						
09/20/2013 20:13		Test Lines	1	3			3500.0	PRESSURE TEST LINES TO 3500 PSI. CHECK FOR VISIBLE LEAKS AND PRESSURE LOSS
09/20/2013 20:19		Pump Spacer 1	2.5	20			200.0	PUMP WATER
09/20/2013 20:23		Pump Spacer 2	5	24			200.0	PUMP MUDDLUSH
09/20/2013 20:32		Pump Spacer 1	5	10			210.0	PUMP WATER
09/20/2013 20:34		Pump Lead Cement	6	188			400.0	PUMP ECONOCHEM CEMENT 558 SKS 12.5 PPG 1.89 CUFT/SK 10.28 GAL/SK MIXED WITH RIG WATER
09/20/2013 21:08		Pump Tail Cement	6	66.5			300.0	PUMP EXPANDACHEM CEMENT 252 SKS 14.6 PPG 1.46 CUFT/SK 6.07 GAL/SK MIXED WITH RIG WATER
09/20/2013 21:24		Shutdown						WASH PUMPS AND LINES ON TOP OF THE PLUG
09/20/2013 21:26		Drop Top Plug						PLUG PRELOADED. WITNESSED BY COMPANY MAN
09/20/2013 21:26		Pump Displacement	6.0	258.8			2300.0	PUMP DISPLACEMENT USING WATER
09/20/2013 21:44		Displ Reached Cmmt						DISPLACEMENT REACHED CEMENT WITH 89 BBL AWAY
09/20/2013 22:13		Bump Plug	3				2171.0	CALCULATED PRESSURE TO LAND WAS 1409. PLUG LANDED WITH 2171 PSI GOING 500 PSI OVER FINAL LIFT

HALLIBURTON

Date/Time	Chart #	Activity Code	Pump Rate	Cum Vol	Pump		Pressure (psig)		Comments
09/20/2013 22:16		Check Floats							PRESSURE WAS HELD FOR 3 MINUTES THEN RELEASED. FLOATS HELD. 2 BBL BACK TO THE TRUCK
09/20/2013 22:18		End Job							23 BBL OF CEMENT BACK TO SURFACE
09/20/2013 22:20		Pre-Rig Down Safety Meeting							DISCUSS RIG DOWN SAFETY AND PROCEDURE
09/20/2013 22:30		Rig-Down Equipment							RIG DOWN ALL EQUIPMENT
09/20/2013 23:20		Safety Meeting - Departing Location							SAFETY MEETING TO DISCUSS JOURNEY BACK TO THE YARD
09/20/2013 23:30		Depart Location for Service Center or Other Site							LEAVE LOCATION FOR THE YARD

Stage/Plug #: 1									
Fluid #	Stage Type	Fluid Name	Qty	Qty uom	Mixing Density lbm/gal	Yield ft ³ /sk	Mix Fluid Gal/sk	Rate bbl/min	Total Mix Fluid Gal/sk
1	MUD FLUSH III	MUD FLUSH III - SBM (528788)	24.00	bbl	8.4			2.5	
2	EconoCem B3	ECONOCEM (TM) SYSTEM (452992)	558.0	sacks	12.5	1.89	10.28	6.0	10.28
2 %		HALLIBURTON GEL, 50 LB SK (100064040)							
3	ExpandaCem B1	EXPANDACEM (TM) SYSTEM (452979)	252.0	sacks	14.6	1.46	6.07	6.0	6.07
6.07 Gal		FRESH WATER							
4	Mud Displacement			bbl	9.8			6.0	
Rates									
Circulating		Mixing		Displacement		Avg. Job			
Cement Left In Pipe		Amount	41.86 ft	Reason	Shoe Joint				
Frac Ring # 1 @	ID	Frac ring # 2 @	ID	Frac Ring # 3 @	ID	Frac Ring # 4 @	ID		
The Information Stated Herein Is Correct				Customer Representative Signature					

