

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400984086

Date Received:

02/04/2016

Spill report taken by:

Kosola, Jason

Spill/Release Point ID:

444653

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: PIONEER NATURAL RESOURCES USA INCOperator No: 10084Address: 5205 N O'CONNOR BLVD STE 200City: IRVINGState: TXZip: 75039Contact Person: James Roybal

Phone Numbers

Phone: (719) 846-7898Mobile: ()Email: james.roybal@pxd.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400980915Initial Report Date: 01/29/2016Date of Discovery: 01/26/2016Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWSW SEC 18 TWP 32S RNG 65W MERIDIAN 6Latitude: 37.251360 Longitude: -104.720470Municipality (if within municipal boundaries): _____ County: LAS ANIMAS

Reference Location:

Facility Type: WATER GATHERING SYSTEM/LINE☒ Facility/Location ID No 427440☐ No Existing Facility or Location ID No.☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): >=1 and <5Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: Warm, sunnySurface Owner: FEE

Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Crews in the area reported a leak at the Muffins 14-18 well site yesterday. It appears the freeze may have caused the above ground gathering line to brake. The lease operator was notified and was isolated upon arrival. It is estimated that 3bbls of produced water were spilled. the water did not leave the locations and No State Waters were involved.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
1/28/2016	COGCC	Jason Kosola	-	email
1/28/2016	LACOG	Bob Lucero	-	email
1/29/2016	Land Owner	Charlie Hagen	-	Phone

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 02/04/2016		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	3	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>50</u>		Width of Impact (feet): <u>1</u>	
Depth of Impact (feet BGS): <u>0</u>		Depth of Impact (inches BGS): <u>0</u>	
How was extent determined?			
Visual inspection and GPS			
Soil/Geology Description:			
From the NRCS soil survey map: Gulnare-Allens Par complex			
Depth to Groundwater (feet BGS) <u>40</u>		Number Water Wells within 1/2 mile radius: <u>3</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>565</u> None <input type="checkbox"/>	Surface Water <u>580</u> None <input type="checkbox"/>	
	Wetlands <u> </u> None <input checked="" type="checkbox"/>	Springs <u> </u> None <input checked="" type="checkbox"/>	
	Livestock <u> </u> None <input checked="" type="checkbox"/>	Occupied Building <u>2900</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:			

At the time the freeze occurred the well was not running just free flowing. An isolation valve will be installed to isolate gathering water from well head when pump is not running. Damaged piece of pipe will be replaced.

CORRECTIVE ACTIONS

#1	Supplemental Report Date: 02/04/2016
Cause of Spill (Check all that apply) <input type="checkbox"/> Human Error <input type="checkbox"/> Equipment Failure <input type="checkbox"/> Historical-Unknown	
<input checked="" type="checkbox"/> Other (specify) Freezing temperatures	
Describe Incident & Root Cause (include specific equipment and point of failure)	
It was determined that inadequate design or installation of original equipment as cause. If there was an isolation valve in place, freeze would not have occurred	
Describe measures taken to prevent the problem(s) from reoccurring:	
Plans are being made to install an isolation valve on the well pad to isolate gathering water from well head.	
Volume of Soil Excavated (cubic yards):	
Disposition of Excavated Soil (attach documentation) <input type="checkbox"/> Offsite Disposal <input type="checkbox"/> Onsite Treatment	
<input type="checkbox"/> Other (specify)	
Volume of Impacted Ground Water Removed (bbls):	
Volume of Impacted Surface Water Removed (bbls):	

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

Produced water quality data from the well associated with or representative of the spill is attached. Pioneer and its consulting geochemical specialists have found, after 20 years operating in the Raton Basin CBM field, that soil sampling no longer adds useful data on smaller, short-term spills as land uses and the environment are not sensitive to short-term exposure to CBM produced water. Effects to soil chemistry from short-term CBM produced water spills are temporary and shallow for several reasons: the water does not contain crude oil or liquid hydrocarbons; the TDS is significantly less than 10,000 mg/L; it is suitable for livestock watering, wildlife and in many cases surface discharge. Mixed with other water it is suitable for irrigation without impact. When requested by the agency or landowner Pioneer has and will collect soil samples. Pioneer Natural Resources request closure of this spill based on this statement and attached water quality data.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: James Roybal
Title: Environmental supervisor Date: 02/04/2016 Email: james.roybal@pxd.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num	Name
400984140	ANALYTICAL RESULTS

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

--	--	--

Total: 0 comment(s)