

Antelope T-21 Pad DWR Water Well Search Results
Weld County - Sec. 21 T5N R62W
Bonanza Creek Energy Operating Company LLC

Well Description	Location	Well Information				Well Status
		Depth	Top Perf	Bottom Perf	Aquifer	
Receipt=9059493, Permit=6062	NW 27	123	0	0	GW	Not maintained/ not equipped (Domestic well)
State of Colorado Land Board	5N-62W					
Receipt=9065626, Permit=81436	NW 21	160	0	0	GW	Not maintained/ not equipped (Stock well)
70 Ranch LLC	5N-62W					
Receipt=0016004, Permit=16004-MH	NE 21	0	0	0	GW	Not representative/ not equipped (Monitoring hole)
Robert Lembke	5N-62W					
Receipt=0018125, Permit=18125-MH	NW 21	77	20	77	GW	Not representative/ not equipped (Monitoring hole)
70 Ranch LLC	5N-62W					
Receipt=0024468, Permit=24468-MH	NE 21	0	0	0	GW	Not representative/ not equipped (Monitoring hole)
Robert Lembke	5N-62W					
Receipt=0024469, Permit=24469-MH	NW 21	0	0	0	GW	Not representative/ not equipped (Monitoring hole)
70 Ranch LLC	5N-62W					
Receipt=0042687, Permit=42687-MH	SE 21	0	0	0	GW	Not representative/ not equipped (Monitoring hole)
70 Ranch LLC	5N-62W					
Receipt=0048354B, Permit=1992017-AB	NW 21	0	0	0	GW	Well Abandoned
70 Ranch LLC	5N-62W					
Receipt=0314638J, Permit=40920-M	NE 21	40	10	40	GW	Not representative/ not equipped (Monitoring hole)
70 Ranch LLC	5N-62W					
Receipt=0336034G, Permit=163752	NE 21	77	20	77	GW	Not representative/ not equipped (Monitoring hole)
70 Ranch LLC	5N-62W					
Receipt=0385493D, Permit=188082	NE 21	25	9	19	GW	Not representative/ not equipped (Monitoring hole)
Robert Lembke	5N-62W					
Receipt=0385493F, Permit=188374	SW 21	40	23	38	GW	Not representative/ not equipped (Monitoring hole)
70 Ranch LLC	5N-62W					