

Water Well Receipt #	Water Well Permit #	QTR	Sec	Reason
464585	0228865--	SE	11	Spoke with landowner by phone on 2/22. On Northern Weld Water and have no water well.
9058269A	0000096-RDB-	NE	12	Landowner declined sampling. Attached. Haythorn property.
9058246	0000074-RD-	NE	12	Landowner declined sampling. Attached. Haythorn property.
0021518	0004834-F-	NE	12	Landowner declined sampling. Attached. Haythorn property.
0022063R	0176000--	SE	12	Landowner declined sampling. Attached. Haythorn property.
0047555	0047555-MH-	SE	12	Landowner declined sampling. Attached. Monitoring well. Fagerberg property.
0048263G	0176000--A	SE	12	Landowner declined sampling. Attached. Fagerberg property.
3649153	0017680--A	SE	12	Landowner declined sampling. Attached. Fagerberg property.
0019164A	0019164-MH-	SE	12	Landowner declined sampling. Attached. Monitoring well. Fagerberg property.
9061625	0013450-R-	SE	12	Landowner declined sampling. Attached. Fagerberg property.
9062463	0017680--	SE	12	Landowner declined sampling. Attached. Fagerberg property.
9058393	0000263-RD-	SW	12	Landowner declined sampling. Attached. Fagerberg property.
9058412	0000276-RD-	SW	12	Landowner declined sampling. Attached. Fagerberg property.
3657700A	0000263-RD-R	SW	12	Landowner declined sampling. Attached. Fagerberg property.
3657700B	0000276-RD-R	SW	12	Landowner declined sampling. Attached. Fagerberg property.
0506832	0013941-R-R	NE	13	Landowner declined sampling. Attached. Fagerberg property.
0102440	0013941-R-R	NE	13	Landowner declined sampling. Attached. Fagerberg property.
9061796	0013941-R-	NE	13	Landowner declined sampling. Attached. Fagerberg property.
9063716	0033924--	NW	13	Well no longer exists. House is on Northern Weld Water
9061797	0013942-R-	NW	13	One irrigation well exists in the quarter section. It is shut in for the winter.
9059264	0004571-R-	NW	13	One irrigation well exists in the quarter section. It is shut in for the winter. See receipt 9061797.
Unable to locate permit		NW	13	Domestic well. Conducted field visit, determined that the well was not in operational condition.