

STATE OF
COLORADO

Andrews - DNR, Doug <doug.andrews@state.co.us>

COGCC Form 2A review of Whiting's Horsetail 30H Pad location - Doc #400967456

2 messages

Andrews - DNR, Doug <doug.andrews@state.co.us>
To: Michael Brown <ml_brown@bresnan.net>

Fri, Feb 5, 2016 at 2:11 PM

Michael,

I have reviewed the referenced Form 2A Oil & Gas Location Assessment and have the following comments.

- 1) In the Location Identification section you have listed the longitude of the reference well (Horsetail #30H-1945) as -103.784433 degrees. However, your Location Drawing and Well Location Plat list the longitude of that well as -103.787358 degrees. Therefore, I would like to change the longitude on the Form 2A to match what is shown on the Location Drawing and Well Location Plat.
- 2) In the Cultural Distance section you have indicated the nearest Above Ground Utility to a well is 450 feet. This agrees with the north facing Location Picture which clearly shows an Above Ground Utility nearby. At 450 feet from the nearest well, this overhead utility line should also be depicted on the Location Drawing, yet no overhead utility is shown. Please revise the Location Drawing to include this overhead utility.

Please respond to this correspondence by March 5, 2016. If you have any questions, please contact me. Thank you.

Doug Andrews

Oil & Gas Location Assessment Specialist - Northeast Area

**COLORADO**Oil & Gas Conservation
Commission

Department of Natural Resources

1120 Lincoln St., Suite 801
Denver, CO 80203
doug.andrews@state.co.us
303-894-2100 Ext. 5180

Michael L. Brown <ml_brown@bresnan.net>
To: "Andrews - DNR, Doug" <doug.andrews@state.co.us>

Wed, Feb 24, 2016 at 9:40 AM

Doug,

Yes please correct the longitude. I have attached a revised location drawing as requested. Please correct the Above Ground Utility to 529'.

Let me know if you need any additional information.

Thanks,

Michael L. Brown

[307-237-9310](tel:307-237-9310)

[Quoted text hidden]



Location Drawing 2-23-16.pdf

183K