

Summary of phone conversations with Monument Global representatives:

2/23/16 5:15 PM

I called Tom Fox to inquire about the lined pit on the Cache Unit #8 location. He told me that the pit was constructed to catch excess cement from the plugging operation. Reportedly, the pit contains fresh water.

I informed Tom of the leaking BOP and he told me that he was not working on that location and that all of the equipment was the property of Red Rock Well Services. He offered to give me their phone number.

Tom said that the holes in the casing have been repaired and that a bridge plug has been set.

The rig has apparently been idle, with no crew, since that time.

I mentioned another rig that Cal and I had seen while in the Cache Unit on 2/23 to Tom. The rig was on a BLM surface well that Tom indicated was a Crystal River operation.

2/24/16 12:45 PM

I called the contact number on the Cache Unit #8 location sign.

I spoke with Kerry Smith and informed him of the leaking well head. He said that he would call Tom Fox and have it fixed. He told me that the well head could not have been leaking for very long and that he had recent pictures of the location.

He informed me that the rig crew had left all of their equipment and that he had been unable to contact them.

2/25/16 9:00 AM

I left a message with Tom Fox regarding any contact from Kerry Smith. I also indicated that the pit contents need to be removed.