



STATE OF COLORADO

Trujillo - DNR, Aaron <aaron.trujillo@state.co.us>

Western Operating- Follow up

1 message

Trujillo - DNR, Aaron <aaron.trujillo@state.co.us>
To: Denise Arthur - DNR <denise.arthur@state.co.us>

Thu, Dec 31, 2015 at 1:11 PM

Denise,

Did a follow-up inspection on Western Operating's Bobcat Sand Unit today.

To refresh your memory, they had issues with stormwater erosion on the battery location and pit. They also had a broken door on a "wooden sub-surface structure".

We had changed the CA date from the end of November to December 31s to repair the door, install SW BMPs and get us a reclamation plan (I sent you the reclamation plan earlier today).

I am including my previous inspection report.

Eric Lang, from their LT, had stated they were working on the repairs in his email to me when they requested an extension. He originally asked for a date od Dec. 23rd, and we gave them to the 31st (today). However, **In my inspection today, I was unable to find any evidence of completed work.** Below is the email send from Mr. Lang, and attached are the photos from today.

Eric Lang <elang@ltenv.com>
to me, steve, Chris

Dec 10 ☆ ↩

Aaron,

I recently had the subject document forwarded to me from my client Steve James at Western Operating. Steve went online and found several other inspections that never made it to his email since the COGCC had his incorrect email listed in their database and he forwarded those to me as well.

LTE and Western are planning to meet with the landowner next week to discuss the reclamation that has been done to date and to discuss what BMPs need to be installed and addressed at the site. As such, we are requesting an extension of the **December 15th** deadline to submit a reclamation plan to the COGCC. We are proposing a new date of **December 23rd** to allow time for this meeting to happen and to discuss the planting schedule and seed mix with the landowner and any earthmoving (if necessary) that may have to be done. In the interim, Western is working on removing weeds and trash from the site and repairing ruts that have exposed piping and repairing the access panel to the pipe junction on the battery pad.

If you have any questions don't hesitate to contact me.

Thank you,


Eric Lang, P.G.
Project Geologist



COMPLIANCE / ENGINEERING / REMEDIATION
LT Environmental, Inc.
4600 West 60th Avenue
Arvada, Colorado 80003
(720) 235-3096 office
(303) 902-7704 cell
(303) 433-1432 fax
www.ltenv.com
elang@ltenv.com

Aaron Trujillo

NE Reclamation Specialist



P 970.867.0808 | C 970.441.1009 | F 970.867.1165

1120 Lincoln Street, Suite 801, Denver, CO 80203 | www.colorado.gov/cogcc

2 attachments

Western_op_Inspection.pdf
115K



435387_SW_Inspection.pdf

5908K