

## Waste Management Plan

Crescent Point Energy US Corporation (Crescent Point) plan for appropriate handling of produced water, drill mud and cuttings, tank bottoms, and other associated exploration and production (E&P) waste is described below:

- E&P wastes onsite will be stored in compatible containers or containment devices designed or engineered for purposes for which they will be utilized. These containers will be inspected on a regular basis to ensure that no undue wear, structural issues, severe rust, or other defects, which may impact their effectiveness.
- E&P wastes will be transported offsite via truck by licensed transporter. Frequency of these operations will vary by site based on waste volumes and ongoing operations.
- Any soils contaminated by E&P waste will be disposed of by a licensed third-party disposal facility/landfill or at a COGCC approved land farm. Tank bottoms will be disposed of at licensed third-party disposal facilities/land farms. Liquid wastes such as flowback fluid and produced water will be disposed of at licensed third party injection facility.
- Drilling wastes such as drill cutting and water based drilling fluids will be reused by land spreading on COGCC approved mud farms per COGCC Rule 907.d.(3). No other E&P wastes will be disposed of at these sites.