

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401052823

Date Received:

05/24/2016

Spill report taken by:

YOUNG, ROB

Spill/Release Point ID:

441818

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>FOUNDATION ENERGY MANAGEMENT LLC</u>	Operator No: <u>10112</u>	<b>Phone Numbers</b>
Address: <u>16000 DALLAS PARKWAY #875</u>		Phone: <u>(918) 526-5591</u>
City: <u>DALLAS</u>	State: <u>TX</u>	Mobile: <u>(918) 636-7239</u>
Zip: <u>75248-6607</u>		Email: <u>regulatory@foundationenergy.com</u>
Contact Person: <u>Caitlin O'Hair</u>		

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400839515

Initial Report Date: 05/14/2015      Date of Discovery: 05/13/2015      Spill Type: Recent Spill

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWSW SEC 36 TWP 2N RNG 47W MERIDIAN 6Latitude: 40.091364 Longitude: -102.583658Municipality (if within municipal boundaries): \_\_\_\_\_ County: YUMA

#### Reference Location:

Facility Type: PIPELINE☐ Facility/Location ID No \_\_\_\_\_☐ No Existing Facility or Location ID No.☒ Well API No. (Only if the reference facility is well) 05-125-11946

#### **Fluid(s) Spilled/Released (please answer Yes/No):**

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): UnknownEstimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0Specify: Unable to fully determine amount of water leak due to rain and rain puddles.

#### **Land Use:**

Current Land Use: CROP LAND

Other(Specify): \_\_\_\_\_

Weather Condition: Continuous rainfall throughout weekSurface Owner: FEEOther(Specify): RMR Ranch Inc., - Donald Ruteledge

#### **Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):**

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A water line leaked yesterday evening 200 yards East of RMR Ranch #14-36 (API#05-125-11946). Foundation Energy Management, LLC. called the COGCC and spoke to Rob Young (COGCC Inspector) on going forward with getting the line cleaned up. As per the spill requirements, Foundation contacted the landowner and Yuma LEPC of the spill. The determination of how much was spilled is unknown because of the present of rainwater on the location's surface. The well has been shut in and the line isolated. A backhoe is scheduled to get on site to repair the line today (if it can make it down from Sterling) and we are getting a vac truck to suck up the standing water/rainwater.

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
5/14/2015	COGCC	Rob Young	303-252-0126	Called by phone and discussed moving forward on drying out the site and sampling.
5/14/2015	Yuma LEPC	yumaoem@wycomm.org	928-317-4680	Notified of spill via email.
5/14/2015	Landowner	Donald Ruteledge	303-570-1836	Talked to crew onsite.

**REQUEST FOR CLOSURE**

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: \_\_\_\_\_

**OPERATOR COMMENTS:**

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Caitlin O'Hair

Title: HSE/Regulatory Tech Date: 05/24/2016 Email: regulatory@foundationenergy.com

**COA Type**

**Description**

--	--

**Attachment Check List**

**Att Doc Num**

**Name**

401052823	FORM 19 SUBMITTED
-----------	-------------------

Total Attach: 1 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

--	--	--

Total: 0 comment(s)