

**Fwd: 34-10 #27-1 FC Spill Report**

1 message

Hughes - DNR, Jim <jimo.hughes@state.co.us>

Wed, Jun 29, 2016 at 8:08 AM

To: OGCC EnviroScan - DNR <dnr_ogcc.enviroscan@state.co.us>, Alex Fischer - DNR <alex.fischer@state.co.us>

Scanning Work Request:

Please upload this e mail as follows:

Document Name(s)	SUITDOE e mail correspondence	
Document Number	(leave blank if not already assigned)	
Date Received	6/29/16	
Is data entry needed?	N	
Indexing Information	Unique ID Type	Unique ID Number
First	API	067-07250
Second	Location	333615
Third		
Additional Instructions	Please upload e mail to referenced IDs	

Thanks!

Jim Hughes

Environmental Protection Specialist


COLORADO
 Oil & Gas Conservation
 Commission

Department of Natural Resources

P.O. Box 4453 Durango, Colorado 81302

jimo.hughes@state.co.us | www.colorado.gov/cogcc

----- Forwarded message -----

From: **Spray, Karen** <kspray@sudoe.us>

Date: Wed, Jun 29, 2016 at 7:32 AM

Subject: RE: 34-10 #27-1 FC Spill Report

To: "Wohlust, Katie" <kawohlust@rwpc.us>, "jimo.hughes@state.co.us" <jimo.hughes@state.co.us>

Cc: SUDOE Spill Reports <spill@sugf.com>, "Bixler, Tom" <tbixler@rwpc.us>, "Kirby, James" <jkirby@rwpc.us>, RW Spills <spill@rwpc.us>

For the purposes of tracking only, this spill has been assigned Tribal spill #2016-0011.

Thank you.

Karen L. Spray, PG

Exploration & Production Manager

Southern Ute Indian Tribe – Growth Fund

Department of Energy

970-563-5556 (office)

970-749-0745 (cell)

kspray@sudoe.us

www.suitdoe.com

From: Wohlust, Katie

Sent: Monday, June 27, 2016 8:18 AM

To: jimo.hughes@state.co.us

Cc: SUDOE Spill Reports <spill@sugf.com>; Bixler, Tom <tbixler@rwpc.us>; Kirby, James <jkirby@rwpc.us>; RW Spills <spill@rwpc.us>

Subject: 34-10 #27-1 FC Spill Report

Jim,

As a courtesy Red Willow is reporting a spill to COGCC.

Red Willow had a 7.8 bbl produced water spill Sunday June 26th at the 34-10 #27-1 FC. Produced water flowed backwards from the main produced water pipeline that leaves location through two ball valves and one check valve to be released on location. All 7.8 bbl of produced water remained on location. No produced water left location. As soon as the lease operator discovered the spill he shut in the pipeline to prevent additional produced water from being released.

Attached are the spill report form, a spill map, and photographs.

Red Willow proposes no further action on this spill. The water quality of produced water near the Fruitland outcrop has low TDS, salts and conductivity. A produced water sample was taken on 1/26/2016 from the #27-1 FC well. TDS was 1470 mg/L.

Please let me know if you have any questions.

Thanks,

Katie

Katie Wohlust

Environmental Compliance Specialist

Red Willow Production Company

14933 Highway 172

P.O. Box 369

Ignacio, CO 81137

Office: [970-563-5288](tel:970-563-5288)

Cell: [970-749-5612](tel:970-749-5612)

