

Date: Mon, Jul 18, 2016 at 12:00 PM
Subject: Re: Hebron 2-07H cuttings pit soil samples.
To: Michael James <mjames@sandridgeenergy.com>
Cc: Alex Fischer - DNR <alex.fischer@state.co.us>

Summary of our phone conversation:

Crews were at the week of 7/11/16 Hebron 2-07H expanding the location. They discovered the old cuttings that were buried by the previous operator. Based on soils observation the excavation crew feels they have reached the extent of the contamination. The estimated size of excavation is approximately 50'x140'x6'.

Sandridge obtained 5 samples from the excavation, 1 in center, 4 quadrants.

Please analyze the Center sample for the full COGCC table 910-1, please include ORO hydrocarbon range. Sample the other four locations for table 910-1, It is acceptable to omit "Metals in Soil" from the other four samples.

Please maintain cuttings as Oily Waste and handle accordingly (rule 907.e).

A final report; describing action taken, demonstration that all contamination was removed, final disposition of waste should be submitted to the COGCC. Work is proceeding without an approved workplan due to the timing of drilling activities, please feel free to contact me to assure we are moving at the appropriate pace.

Thank You,

Kris Neidel
Environmental Protection Specialist Northwest Area
Colorado Oil and Gas Conservation Commission
Office [970-871-1963](tel:970-871-1963)
Cell [970-846-5097](tel:970-846-5097)



On Fri, Jul 15, 2016 at 11:29 AM, Michael James <mjames@sandridgeenergy.com> wrote:

Kris

What test are required on the soil samples for the Hebron 2-07H cuttings pit?

Michael James

EH&S Technician 2

[405-519-6634](tel:405-519-6634)

