

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/21/2016

Submitted Date:

09/22/2016

Document Number:

679700255**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
ALLISON, RICK 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION AND PRODUCTION LLCAddress: 730 17TH ST STE 610City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Miller, Meagan	832-746-8446	mmiller@bayswater.us	
Axelson, John		john.axelson@state.co.us	
Barbula, Don	303-912-4213	dbarbula@bayswater.us	
Brown, Mark	303-893-2503	mbrown@bayswater.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441086	LAND APPLICATION SITE	AC	03/27/2015		-	Cockroft Farms	EI

General Comment:

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Piles	Inadequate		
Comment	It appears the free oil noted in Inspection Doc#679700232 has been removed. Stormwater and/or irrigation runoff has ponded in the area where oily liquid was previously observed. Drill cuttings remain stockpiled both north of the alfalfa crop and southeast of the area near the PDC Cockroft 19V location. These cuttings cannot be stored long term over the winter.			
Corrective Action	The Operator needs to develop a plan to manage the cuttings so that the cuttings do not accumulate in stockpiles for long periods of time with no action. The Operator shall ensure all currently stockpiled cuttings are spread and incorporated or disposed prior to the development of freezing condition. The cuttings need to either be amended/composted with manure as described in the waste management plan, or incorporated on agricultural land. The Waste Management Plan needs to show any new areas where cuttings will be spread and incorporated and include a timeframe for the incorporation. Corrective Action Date on this inspection refers to the due date for the revised Corrective Action Plan.			Date: 10/24/2016

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): Comment: Pilot: Wildlife Protection Devices (fired vessels): **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700256	Figure 2 from WMP with COGCC notes	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3959091
679700260	Cockroft Land Application Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3959092