

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2016

Submitted Date:

09/27/2016

Document Number:

680301114

**FIELD INSPECTION FORM**

Loc ID 312144 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
7 Number of Comments  
4 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 7800  
 Name of Operator: BEREN CORPORATION  
 Address: 2020 N BRAMBLEWOOD STREET  
 City: WICHITA State: KS Zip: 67206

**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Young, Rob		rob.young@state.co.us	
Reynolds, Rodney	316-337-8340	reynoldsr@berexco.com	
Quint, Craig		craig.quint@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218987	WELL	PR	06/25/1954	OW	075-05793	BREWER 'A' 3	PR

**General Comment:**  
 Routine Site Inspection - PW from related well (075-05793) is being directed to injection well (075-05797). PW pits are in the process of being vacated. PW evaporation process has possibly reached static ground water level based on surrounding cropland ground water levels, affecting further evaporation of remaining PW contained within pits. Weeds have over-grown on PW pits and surrounding area @ pits. Weed control requirement cited on previous COGCC Doc# 680300173 & 680300174. Crude Oil exhibited within berms and inside slopes of PW pits, including site location of former skim pit. Quantity of affected soils in undetermined as of date of FIR Doc# 680301114. See attached photographs for documentation. Note to Operator: Please contact COGCC Environmental Group for directives.

<b>Location</b>					
<b>Lease Road:</b>					
Type	Access				
comment:	Located within cropland, entrance off County Road 32, Logan County.				
Corrective Action					Date:
Overall Good: <input type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	WELLHEAD				
Comment:					
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Emergency Contact No. - satisfactory				Date:
Corrective Action:					Date: _____
<b>Good Housekeeping:</b>					
Type	WEEDS				
Comment:					
Corrective Action:	Control weeds on location. See attached photographs.				Date: 10/28/2016
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
Crude Oil					
Comment:	Crude Oil saturated soils on inside slopes and within berms of PW pits. See attached photographs.				
Corrective Action:	Remove/Remediate effected soils @ PW pits. PW pits are in the process of being vacated, PW is being directed to injection well (075-05797). Contact COGCC Enironmental Group for directives. Corrective Action date set by Rule, landowner has crop in surrounding field which should be harvested/removed by Dec. 1, 2016. Spill/Release is inactive, coordinate with COGCC Environmental Group for removal/remediation dates and all corrective action compliance.				Date: 09/29/2016
In Containment: Yes _____					
Comment:	PW pits are in the process of evaporation and being vacated. PW levels remaining in pits have possibly reached static ground water level. PW is being directed to injection well (075-05797). Operator Note: Please contact COGCC Environmental Group for directives. Landowner has crop in surrounding field as of date of FIR, spill/release is inactive, coordinate with COGCC Environmental Group for removal/remediation dates for corrective actions/compliance.				
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type					
Comment:					
Corrective Action:					Date:
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	2	200 BBLS	STEEL AST		40.654692,-103.279061
Comment:					

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate	
Comment:					
Corrective Action:	Remove/Remediate affected soils within and upon berms @ PW pits. Control weeds on location.			Date:	10/28/2016

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 218987 Type: WELL API Number: 075-05793 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Facility Inspection - Weed control non-compliance and Spill/Release exhibited within and upon soils @ PW pits currently in process of vacating PW pits. Related PR \(075-05793\) & Inj. \(075-05797\).](#)

Corrective Action:

Date:

**Environmental**

**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: Crude Oil exhibited within and upon inside slopes of PW pits being currently vacated. Contact COGCC Environmental Group for directives. Volume/Quantity of spill/affected soils is undetermined on date of FIR Doc# 680301114. Spill/Release is inactive. Possible ground water exposure.

Corrective Action: Landowner has crop in surrounding field. Coordinate removal/remediation with COGCC

Date: 09/29/2016

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: 0 Depth to Ground Water: 0

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Note to Operator: Please contact COGCC Environmental Group for directives.	schureky	09/27/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680301114	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962182">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962182</a>
680301143	Weeds on berm - oil surfacing @ former skim pit site	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962132">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962132</a>
680301144	Crude surfacing @ former skim pit site	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962133">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962133</a>
680301145	Crude oil saturated soils within PW pit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962134">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962134</a>
680301146	Weeds on berm	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962135">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962135</a>
680301147	Crude oil on inside slope of PW pit berm	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962136">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962136</a>
680301148	Crude oil saturated soils inside slope of PW pit berm	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962137">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962137</a>
680301149	Crude oil saturated soils inside slope of PW pit berm	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962138">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962138</a>
680301150	Crude oil saturated soils within PW berm	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962139">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962139</a>
680301151	Crude oil saturated soils inside slope of PW pit berm	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962140">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962140</a>
680301152	Weeds on berms @ PW pit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962141">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962141</a>
680301153	Crude oil saturated soils on inside slope of PW pit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962142">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962142</a>

680301154	Weeds on berms @ PW pits	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962143">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962143</a>
680301155	Crude oil saturated soils inside slope of PW pit berm	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962144">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3962144</a>