

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2016

Submitted Date:

10/04/2016

Document Number:

675102980**FIELD INSPECTION FORM**

Loc ID 398432 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 BROADWAY STE 2300City: DENVER State: CO Zip: 80290**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
CO, Western	303-876-7091	whitingwesternco@whiting.com	Western slope inspection

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429256	WELL	PR	12/01/2012	OG	103-11931	WRD 23-33R	WK

General Comment:On location in regards to Form 42 doc # 401096542 " Start of plugging operations notice"

Inspected FacilitiesFacility ID: 429256 Type: WELL API Number: 103-11931 Status: PR Insp. Status: WK**Workover**

Comment: C&J workover rig on location - Cutters Wireline went in hole to tag top of cement with a weight bar and collar locator. Top of cement tagged at 10,496' Discussed next steps to plug well - modified plugging schedule was sent to both COGCC and BLM engineering office.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675102980	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3968026