

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2016

Submitted Date:

10/05/2016

Document Number:

673803759**FIELD INSPECTION FORM**
 Loc ID 424057 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 2800Name of Operator: ANADARKO E&P ONSHORE LLCAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Findings:**12 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424055	WELL	PR	05/15/2014	GW	123-33866	CHRISTNER 8-66-5-3XH	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	NO LABEL ON TANK		
Corrective Action:	INSTALL SIGN TO COMPLY WITH RULE 210d.	Date:	11/07/2016
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	weeds around pad		
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "	Date:	10/17/2016

Overall Good: ☐

Spills:			
Type	Area	Volume	
Other	Pump Jack	<= 1 bbl	
Comment:	APPROX 4'X3' STAINED SOIL ON NORTH SIDE OF PUMP JACK 2ND SPILL NORTH SIDE OF PUMP JACK 4'X4' STAINED SOIL		
Corrective Action:	"Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff." CLEAN UP ALL SATINED SOIL ON LOCATION		Date: 11/07/2016
Other	Tank	<= 1 bbl	
Comment:	2ND SPILL NORTH SIDE OF PUMP JACK SOUTH SIDE OF SMALL TANK 4'X4' STAINED SOIL		
Corrective Action:	"Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff." CLEAN UP ALL SATINED SOIL ON LOCATION		Date: 11/07/2016

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	WIRE		
Corrective Action:		Date:	

Type	OTHER		
Comment:	FLARE/AG PANEL		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	WIRE		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	1	400 BBLS	FIBERGLASS AST		40.695620,-104.804470	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate
Comment:						
Corrective Action:		Date:				
Contents	#	Capacity	Type	Tanak ID	SE GPS	
	1		FIBERGLASS AST		40.695900,-104.805160	
Comment:						
Corrective Action:		Date:				
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Earth	Inadequate	Walls Insufficient		Base Insufficient		Inadequate
Comment:		Berms on tanks are eroded, not being maintained in good condition Berms should be able to contain 150% of largest single tank and inspected and maintained in good condition.				
Corrective Action:		"Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G." Date: 10/24/2016				
Contents	#	Capacity	Type	Tanak ID	SE GPS	
CRUDE OIL	5	400 BBLS	STEEL AST		40.695620,-104.804470	
Comment:						
Corrective Action:		Date:				
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate
Comment:						
Corrective Action:		Date:				
<u>Venting:</u>						
Yes/No	NO					
Comment:						

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	424055	Type:	WELL	API Number:	123-33866	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: EQUIPMENT ONSITE									
Comment: SI									
Corrective Action: Date:									
BradenHead									
Comment: PLUMBED TO SURFACE									
Corrective Action: Date:									

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	SI
Pilot: OFF	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673803759	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3969741
673803760	STAINED SOIL	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3969722
673803761	WEEDS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3969723
673803762	NO LABELS/BERMS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3969724