

## Federal-Chamberlin 22-1

Inspection# 673403738

Separators less than 50 feet  
from heated tanks.



Dried vegetation at  
wellhead. Stained soil at  
wellhead.

