

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/14/2016

Submitted Date:

10/14/2016

Document Number:

675203428**FIELD INSPECTION FORM**
 Loc ID 322402 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 16000 DALLAS PARKWAY #875City: DALLAS State: TX Zip: 75248-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Giboo, David	(970) 319-2211	dgiboo@blm.com	Lead Petroleum Engineering Tech
Contact, General		regulatory@foundationenergy.com	Regulatory
Allred, Josh	(970) 629-5914	jallred@foundationenergy.com	Field Supervisor
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor

General Comment:Follow up to inspection Doc#675203167. COGCC staff could not access location.

Location**Lease Road:**

Type	Access		
comment:	Access road is washed out.		
Corrective Action:	Maintain and repair access roads per Rule 604.c.(2)S.	Date:	11/14/2016

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203434	Washed out access	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3977578