

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/14/2016

Submitted Date:

10/15/2016

Document Number:

675203435**FIELD INSPECTION FORM**

Loc ID 323804 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 16000 DALLAS PARKWAY #875City: DALLAS State: TX Zip: 75248-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		regulatory@foundationenergy.com	Regulatory
Giboo, David	(970) 319-2211	dgiboo@blm.com	Lead Petroleum Engineering Tech
Allred, Josh	(970) 629-5914	jallred@foundationenergy.com	Field Supervisor

General Comment:COGCC staff could not access location. Road is washed out.

Location**Lease Road:**

Type	Access		
comment:	Road is washed out. See attached photos.		
Corrective Action:	Maintain and repair access roads per Rule 604.c.(2)S.	Date:	11/15/2016

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203436	Washed out access road.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3977579