

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2016

Submitted Date:

10/18/2016

Document Number:

685501025**FIELD INSPECTION FORM**
 Loc ID 320211 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 3990Name of Operator: ARGONEX COMPANY LLCAddress: 8578 A GOLDEN PEAK DRIVECity: HIGHLANDS State: CO Zip: 80130**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments10 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Behrens, Vic	(303) 810-6382	behrens@netecin.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203066	WELL	PR	04/30/2006	OW	001-08472	CHAMPLIN (HER) 1-1	PR

General Comment:

Location				
Lease Road:				
Type	Main			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	CAN'T READ BATTERY SIGN NEED NEW SIGN			
Corrective Action:	Signs and Markers		Date:	11/18/2016
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:			Date:	
Type	CONTAINERS			
Comment:				
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	NEED NEW SIGN CAN'T READ IT			
Corrective Action:	Signs and Markers		Date:	11/18/2016
Emergency Contact Number:				
Comment:	NO EMERGENCY CONTACT NUMBER			
Corrective Action:	Signs and Markers		Date:	11/18/2016
Good Housekeeping:				
Type	TRASH			
Comment:	TRASH INSIDE TREATER HOUSE, PUMP HOUSE TRASH 5 GALLON BUCKETS, THIEF HATCHES INSIDE BERMS			
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "		Date:	
Type	UNUSED EQUIPMENT			
Comment:	REMOVE 300 BBL TANK UNUSED EQUIPMENT			
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "		Date:	11/18/2016
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Crude Oil	Treater	<= 1 bbl		
Comment:	soiled dirt inside treater house			
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "		Date:	11/18/2016
Crude Oil	Pump Jack	<= 1 bbl		
Comment:	soiled dirt inside pump jack house between motor mounts need cleaned out			

Corrective Action: "Comply with Rule 603.f using the Rule 603.f guidance document for further details. "	Date: 11/18/2016
----------------------------------------------------------------------------------------------------------	------------------

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:		corrective date
Type: Vertical Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT		,
Comment:	need capacity signage				
Corrective Action:	"Install sign to comply with Rule 210.b."				Date: 11/18/2016

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	berms in dis-repair			
Corrective Action:	"Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G."			Date: 11/18/2016

Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		39.998830,-104.342180
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	berms in dis-repair will not hold capacity of oil prod tank			
Corrective Action:	"Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G."			Date: 11/18/2016

Venting:

Yes/No	NO	
Comment:	NO AIRS NUMBER	
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 203066	Type: WELL	API Number: 001-08472	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:			Date:	

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
	montoyaj	10/18/2016

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685501028	well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979511
685501029	soiled dirt	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979512
685501030	trash and soiled dirt	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979513
685501031	oil spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979514
685501032	trash and recycle pump	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979515
685501033	trash	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979516
685501034	battery sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979517
685501036	unused tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979518
685501037	unused equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979519
685501038	soiled dirt concrete vault	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979520
685501039	soiled dirt	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979521
685501040	fill in holes around pit screen	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979522
685501041	repair fence pit screen	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979523
685501042	low spot on pit screen	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979524
685501043	berms need rebuilt	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3979525