

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401137427

Date Issued:
10/27/2016

NOTICE OF ALLEGED VIOLATION - ISSUED

Per Rule 522, the Director has reasonable cause to believe that a violation of the Act, or of any Commission rule, order, or permit has occurred, the Director will require the operator to remedy the violation and may commence an enforcement action seeking penalties by issuing a Notice of Alleged Violation (NOAV). Per Rule 523, an operator who violates the Act, or a Commission rule, order, or permit may be subject to a penalty imposed by Commission order.

OPERATOR INFORMATION

OGCC Operator Number: <u>96155</u>	Contact Name and Telephone:
Name of Operator: <u>WHITING OIL & GAS CORPORATION</u>	Name: <u>Scott Webb</u>
Address: <u>1700 BROADWAY STE 2300</u>	Phone: <u>(303) 390-4095</u> Fax: <u>(303) 390-4943</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80290</u>	Email: <u>scottw@whiting.com</u>

Well Location, or Facility Information (if applicable):

API Number: <u>05-123-41840-00</u>	Facility or Location ID: _____
Name: <u>Horsetail</u>	Number: <u>07H-1816</u>
QtrQtr: <u>SENE</u> Sec: <u>7</u>	Twp: <u>10N</u> Range: <u>57W</u> Meridian: <u>6</u>
County: <u>WELD</u>	

ALLEGED VIOLATION

Rule: 317.p

Rule Description: Requirement to Log Well

Initial Discovery Date: _____ Was this violation self-reported by the operator? Yes

Date of Violation: _____ Approximate Time of Violation: _____

Was this a discrete violation of obvious duration? Yes

Description of Alleged Violation:

Pursuant to Rule 317.p., Operator was required to run a minimum of a resistivity log with gamma-ray or other petrophysical log(s) approved by the Director that adequately describe the stratigraphy of the wellbore, and submit the log with the Drilling Completion Report – Form 5. This requirement was modified in the approved Form 2 to require one open hole resistivity log with gamma-ray from total depth to the surface casing for one of the first wells drilled on the pad. Operator failed to perform the open hole resistivity log on any well on this pad, violating Rule 317.p, (also violating section 34-60-121(1) C.R.S. by violating terms of a permit).

Abatement or Corrective Action Required to be Performed by Operator: _____ Corrective Action Due Date: 11/25/2016

Proper and timely abatement does not preclude the assessment of penalties and an Order Finding Violation.

Operator shall submit a Form 4 Sundry Notice to detail internal procedures that will ensure that the requirement for running an open hole resistivity log with gamma ray on a minimum of one well per pad and submitting that log on the Form 5 is met in the future.

PENALTY

Penalties for violations alleged in this NOAV will be calculated pursuant to Rule 523, with daily penalties accruing pursuant to Section 34-60-121(1), C.R.S.

ANSWER

Pursuant to Rule 522.d.(2), the operator must file an Answer to this NOAV within 28 days of its receipt, or a default judgement may be entered. Hard copy answers are filed with the Commission Secretary at the Commission's Denver office and should also be emailed to dnr_cogccenforcement@state.co.us.

NOAV ISSUED

NOAV Issue Date: 10/27/2016

COGCC Representative Signature: *Barbara Westerdale*

COGCC Representative: Barbara Westerdale

Title: Permit/Completion Supervi

Email: barbara.westerdale@state.co.us

Phone Num: (303) 894-2100x5159

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401137867	NOAV COVER LETTER
401137868	NOAV CERTIFIED MAIL RECEIPT

Total Attach: 2 Files