



Alfred Ward & Son

66 Years Production, Operations, Exploration

Monday, September 19, 2016

State of Colorado Oil and Gas Conservation Commission
1120 Lincoln St., Ste. 801
Denver, CO 80203

RE: NOAV for API # 05-121-08878-00; Blomenkamp #1, SWNE Sec. 20 T3S
R56W; Washington County, Colorado

Gentlemen:

In response to this NOAV I have the following comment.


Due to low prices and net cash flow, I had to prioritize work to be done in the field. Since we have a UIC well problem excess resources were directed to the Pierce #4 in the Big Beaver field.

During the MIT of that well I did inform Susan that our next project was to plug and abandon the aforementioned well and will be filing notice and a plan shortly.

As to the filing of past production records, that process has been started.

The well was not a high priority with me as the bottom hole pressure is very low and had no chance of affecting the usable waters of the State.

Sincerely,



Randy Ward

Alfred Ward & Son

66 Years Production, Operations, Exploration

Monday, September 19, 2016

State of Colorado Oil and Gas Conservation Commission
1120 Lincoln St., Ste. 801
Denver, CO 80203

RE: NOAV for API 05-075-09361-00 Michaels #2; SWSW Sec. 14 T11N R53W;
Logan County, Colorado


Gentlemen:

Due to low prices and small cash flow, priority was given to the repair of our UIC well in Washington County, Colorado.

We did however in July have a rig in the area, set a cast iron bridge plug over the J Sand with cement and commenced testing D Sand intervals. Currently the well is scheduled to be swabbed and gas pressure noted to evaluate either further completion methods or plugging and abandonment.

Production reports have been begun to be filed. They should be in current status shortly.

Sincerely,



Randy Ward