

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2016

Submitted Date:

11/03/2016

Document Number:

685301722

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
325616 _____ St John, William (Cal) _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 380 AIRPORT RD
 City: DURANGO State: CO Zip: 81303

Findings:

- 13 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215110	WELL	PR	06/30/1986	GW	067-06715	FEDERAL 02L-01 #1	PR

General Comment:

Inspection report contains corrective action and comment. See Good Housekeeping and Stormwater Sections of report for additional details. See link at end of report for path to downloadable pictures.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Thistle is growing along perimeter of location.		
Corrective Action:	Remove Thistle to comply with Rule 603.f using the Rule 603.f guidance for further details.		Date: 11/15/2016
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Post and Wire		
Corrective Action:			Date:
Type	OTHER		
Comment:	Telemetry Equipment - Panel		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Panel -Includes Gas Meter Run		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Telemetry Equipment		

Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 215110 Type: WELL API Number: 067-06715 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
TRANSECT RESULTS OF DISTURBED AREA% _____
TRANSECT RESULTS OF REFERENCE AREA% _____
TOTAL % OF DESIRABLE VEGETATION COVER _____
VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
TRANSECT RESULTS OF DISTURBED AREA% _____
TRANSECT RESULTS OF REFERENCE AREA% _____
TOTAL % OF DESIRABLE VEGETATION COVER _____
VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Rip Rap	Pass					
Compaction	Fail	Culverts	Pass			
Berms	Pass	Compaction	Pass			
Ditches	Pass	Gravel	Pass			

Comment: [Erosion channels on SW corner fill slope.](#)

Corrective Action: [Install or repair required BMPs to comply with Rule 1002.f. Refer to 1002.f guidance document for further details.](#)

Date: 12/06/2016

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301735	Thistles on perimeter 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993426
685301737	Erosion Channels	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993427
685301738	Thistles on perimeter 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993428