

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/04/2016

Submitted Date:

11/04/2016

Document Number:

684902529**FIELD INSPECTION FORM**

Loc ID 332911 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
LARA-MESA, SUSANA	303-825-4822	cogcc@kpk.com	VP OF ENGINEER

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244760	WELL	PR	03/05/1986	OW	123-12555	ROLLIE J VINCENT A 1	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds around separator, battery, in battery berms, around wellhead		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	11/14/2016

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Stained soil in separator house		

Corrective Action:	Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.		Date:	12/05/2016
Type: Prime Mover	# 1			
Comment:	electric			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	stained soil at wellhead			
Corrective Action:	Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.		Date:	12/05/2016

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV CONCRETE		40.170190,-104.856380
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	50bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shared with crude oil				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.170190,-104.856380
Comment:	Stained soil at loadouts				
Corrective Action:	Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.				Date:
					12/05/2016

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Inspected FacilitiesFacility ID: 244760 Type: WELL API Number: 123-12555 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SI. About to be put back into production according to relief pumper.Corrective Action: Date: **BradenHead**Comment: Bradenhead plumbed to surface.Corrective Action: Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684902530	Stained soil at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993971
684902531	Weeds around tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993972
684902532	Stained soil at loadout	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993973
684902533	Stained soil at loadout	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993974
684902534	Weeds in tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993975
684902535	Weeds around separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993976
684902536	Stained soil in separator house	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993977