

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401143567
Date Received:
11/04/2016

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: PO BOX 6501
City: ENGLEWOOD State: CO Zip: 80155
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Begano, Mary	719-859-1918/719-846-2102	mary_begano@xtoenergy.com
Harrison, Lyndon	505-333-3100	Lyndon_Harrison@xtoenergy.com
Trujillo, Irwin		irwin_trujillo@xtoenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 673503737
Inspection Date: 09/16/2016 FIR Submit Date: 09/22/2016 FIR Status:

Inspected Operator Information:

Company Name: XTO ENERGY INC Company Number: 100264
Address: PO BOX 6501
City: ENGLEWOOD State: CO Zip: 80155

LOCATION - Location ID: 309291

Location Name: GOLDEN EAGLE-633S67W Number: 30SENW County: LAS ANIMAS
Qtrqtr: NENW Sec: 30 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.146672 Longitude: -104.928421

FACILITY - API Number: 05-071-00 Facility ID: 291279

Facility Name: GOLDEN EAGLE Number: 30-3
Qtrqtr: NENW Sec: 30 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.146672 Longitude: -104.928421

CORRECTIVE ACTIONS:

1 CA# 53043

Corrective Action: Stabilize and reclaim the northwest cut slope. Date: 11/30/2016

Response: CA COMPLETED Date of Completion: 10/31/2016

Operator Comment: Mopped out the rill formations along the cut slope and re-seeded using fertilizer, soil enhancers and Flexterra High Performance Growth Medium. See attached photos.

COGCC Decision: Approved

COGCC Representative:

[Empty box for COGCC Representative]

2 CA# 53044

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 10/14/2016

Response: CA COMPLETED

Date of Completion: 10/31/2016

Operator Comment: Installed road base and crowned the driving surface to establish sheet flow. Installed rip rap in bar ditch to stabilize and prevent erosion. Sediment accumulation was removed from culvert inlet. A portion of road was raised to install a new culvert along the main access road. See attached photos.

COGCC Decision: Approved

COGCC Representative:

[Empty box for COGCC Representative]

OPERATOR COMMENT AND SUBMITTAL

Comment:

[Empty box for Operator Comment]

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kelly Kardos

Signed: _____

Title: Permitting Supervisor

Date: 11/4/2016 3:35:57 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401143567	FIR RESOLUTION SUBMITTED
401143578	After Photos

Total Attach: 2 Files