

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2016

Submitted Date:

11/17/2016

Document Number:

678200526**FIELD INSPECTION FORM**
 Loc ID 316966 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 94300Name of Operator: WARD & SON\* ALFREDAddress: P O BOX 737City: OGALLALLA State: NE Zip: 69153**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ward, Randy	308-284-8350	rlwardne@charter.net	
Ward, Randy	308-284-8350	randy@wardoil.com	
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107664	PIT	AC			-	BLOMENKAMP	EI
117793	PIT	AC			-	BLOMENKAMP	EI

**General Comment:**Environmental inspection related to Rem #9290.

**Inspected Facilities**

Facility ID: 107664	Type: PIT	API Number: -	Status: AC	Insp. Status: EI
---------------------	-----------	---------------	------------	------------------

Facility ID: 117793	Type: PIT	API Number: -	Status: AC	Insp. Status: EI
---------------------	-----------	---------------	------------	------------------

**COGCC Comments**

Comment	User	Date
Contact NE EPS to arrange schedule for implementation of Rem #9286 including Conditions of Approval by November 30, 2016.	youngr	11/17/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678200528	Open excavation N of OSP showing recent produced water dump line repair	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006359">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006359</a>
678200529	Mudcracks inside and outside containment berm at dump line repair location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006360">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006360</a>
678200530	Weeds on pit berms, mud cracks and backhoe tire tracks from uncontained spill, view S	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006361">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006361</a>
678200531	Oil skim pit, pipe repairs, mud cracks in and out of PW tank berm	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006362">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006362</a>
678200532	Leaking wellhead, soil on plastic S of wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006363">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4006363</a>