



Whiting Petroleum Corporation
and its wholly owned subsidiary
Whiting Oil and Gas Corporation

1700 Broadway, Suite 2300, Denver, CO 80290-2300
Phone: 303.837.1661 | FAX: 303.861.4023

October 31, 2016

Re: Safety Standards for Maintaining a Preset Conductor - Certification

Dear Mr. Kopp:

On October 28, 2016, my team inspected the following preset conductors to evaluate if they meet the Section 4.a. "Safety Standards for Maintaining a Preset Conductor" as included in the "Notice to Operators: Procedures for Preset Conductors" dated September 1, 2016. Based upon these field inspections the following preset conductors meet the requirements of Section 4.a:

Razor 22D:	2205a, 2701A, 2206B, and 2704B
Razor 25B:	2451, 2450, 2449, and 2550
Razor 25N:	2440
Horsetail 07F:	1840, 1837, 0638, 1838, and 0637
Horsetail 07G:	1844, 1842, 1841, 0642, and 0644
Horsetail 07H:	1845, 0614, and 0646
Razor 11F:	0208B, 0207A, 1408B, and 1407A
Razor 11G:	0211A, 1412B, and 1411A
Razor 11H:	0213A, 1413A, 1416B, 0216B

If you have questions or require additional information, please contact me at (970) 407-3008.

Yours truly,

A handwritten signature in black ink, appearing to read "Kyle", written over a white rectangular background.

Kyle Waggoner
Field Regulatory Manager