

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2016

Submitted Date:

11/18/2016

Document Number:

685501392**FIELD INSPECTION FORM**
 Loc ID 320177 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Espinosa, Bill		billespinosa30@yahoo.com	<a href="#">Inspections</a>
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>
Condill, J.B.		jbcrog@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202912	WELL	PR	09/07/1994	OW	001-08317	WALKER ANN 2	PR

**General Comment:**

Location				
<b>Lease Road:</b>				
Type	Main			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	OK			
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	THIS SOILED DIRT NEEDS TO BE REMOVED INSTEAD OF POUTTING MORE DIRT ON THE STAINED SOIL			
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "			Date: <u>12/02/2016</u>
Crude Oil	Truck Loadout	<= 1 bbl		
Comment:	NEED CAP ON LOAD LINE			
Corrective Action:	"Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O."			Date: <u>12/02/2016</u>
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	BARBWIRE FENCE			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Pump Jack	# 1			corrective date
Comment:	PLATE ON MUFFLER THE BOLTS ARE STRIPPED NEEDS TO BE RETHREADED OR WELDED SHUT			
Corrective Action:	"Location is within a designated setback location, a leak detection plan is required. Fix the identified leak and then Implement the leak detection plan to ensure other leaks do not exist per Rule 604.c.(2)F."			Date: <u>12/02/2016</u>
<b>Venting:</b>				
Yes/No	NO			
Comment:				

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 202912 Type: WELL API Number: 001-08317 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

THE MUFFLER PLATE BOLTS ARE STRIPPED AND NEED TO BE REPAIRED AND STAINED SOIL CLEANED UP

montoyaj

11/18/2016

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685501392	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4012400">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4012400</a>
685501393	SOILED DIRT NEEDS REMOVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007112">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007112</a>
685501394	BOLTS ARE STRIPPED WILL NOT HOLD PLATE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007113">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007113</a>
685501395	WELL SITE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007114">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007114</a>
685501396	NEED CAP ON LOAD LINE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007115">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007115</a>
685501397	BATTERY SIGN	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007116">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007116</a>