

Construction and Stormwater Inspection




Photo 1. Photo taken from the southeast corner, facing West. No BMPs. Stormwater and erosion control BMPs need to be installed prior to the start of construction.

Construction and Stormwater Inspection




Photo 2. Photo taken from the southeast corner, facing North, towards the topsoil stockpile. No BMPs. Stormwater and erosion control BMPs need to be installed prior to the start of construction.

Construction and Stormwater Inspection



Photo 3. Photo taken from approximate center of location, facing East, towards the topsoil stockpile. Topsoil salvage IN-PROCESS.

Construction and Stormwater Inspection



Photo 4. Photo taken from the western location, facing South. No BMPs. Stormwater and erosion control BMPs need to be installed prior to the start of construction.

Construction and Stormwater Inspection




Photo 5. Photo taken from the northern location, facing West. No BMPs. Stormwater and erosion control BMPs need to be installed prior to the start of construction.