

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2016

Submitted Date:

12/14/2016

Document Number:

682401615**FIELD INSPECTION FORM**
 Loc ID 445257 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445253	WELL	XX	03/29/2016		123-42980	Hazzard Federal LC22-735	CI
445254	WELL	XX	03/29/2016		123-42981	Dukes Federal LC10-745	CI
445255	WELL	XX	03/29/2016		123-42982	Dukes Federal LC10-735	CI
445256	WELL	XX	03/29/2016		123-42983	Hazzard Federal LC22-745	CI
445258	WELL	XX	03/29/2016		123-42984	Hazzard Federal LC22-740	CI

General Comment:

This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401162219.

Location Construction

Location ID: 445257 CDP: _____

Comment: Additional inspections will proceed as location is completed.

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
SLOPE ROUGHENING	Yes		

Comments: Erosion BMPs: Surface roughening, which is a temporary BMP, was installed around the perimeter of the location.

Other BMPs: _____

Corrective Action: _____

Date: _____

Comment: _____

Topsoil stockpile stored along the southern location. Topsoil shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production operations. Best management practices to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action: _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>445253</u>	Type: <u>WELL</u>	API Number: <u>123-42980</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445254</u>	Type: <u>WELL</u>	API Number: <u>123-42981</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445255</u>	Type: <u>WELL</u>	API Number: <u>123-42982</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445256</u>	Type: <u>WELL</u>	API Number: <u>123-42983</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445258</u>	Type: <u>WELL</u>	API Number: <u>123-42984</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

COGCC Comments

Comment	User	Date
Refer to attached inspection photos in Document #682401617.	binschusc	12/14/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401617	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4027768